James H. Hohenstein Christopher R. Nolan Lissa D. Schaupp HOLLAND & KNIGHT LLP 195 Broadway New York, NY 10007-3189

Tel: (212) 513-3200 Fax: (212) 385-9010

E-mail: jim.hohenstein@hklaw.com

chris.nolan@hklaw.com lissa.schaupp@hklaw.com

Attorneys for Plaintiff Fouquet Sacop S.A.

UNITED STATES DISTRICT COURT SOUTHERN DISTRICT OF NEW YORK

FOUQUET SACOP S.A.,

Plaintiff,


-against-

YARDIMCI GEMI INSA A.S.,

Defendant.

JUCEKAPIAN

09 CIV 7501



09 CV _____ ()

VERIFIED COMPLAINT

Plaintiff Fouquet Sacop S.A. ("Plaintiff" or "Fouquet"), by and through its attorneys, Holland & Knight LLP, for its verified complaint against Yardimci Gemi Insa A.S., ("Yardimci") alleges as follows:

This is a case of admiralty and maritime jurisdiction under 28 U.S.C. § 1333 as 1. hereinafter more fully appears and is a maritime claim within the meaning of Rule 9(h) of the Federal Rules of Civil Procedure.

- 2. At all times material herein, plaintiff Fouquet was and is a business entity organized and existing under the laws of France with a registered office at 112, boulevard des Dames, 13002 Marseille, France.
- 3. Upon information and belief, at all material times herein, defendant Yardimci was and is a business entity organized under the laws of the Republic of Turkey with a registered office at Aydintepe Mahallesi, Tersaneler Caddesi 50, Sokak No. 7, 81700 Tuzla, Istanbul, Turkey.
- 4. On December 17, 2003, Fouquet and Yardimci entered into a contract ("Contract"). Pursuant to the terms of the Contract, Yardimci undertook to build one tank vessel for the carriage of molten sulphur, asphalt or bitumen (the "FS Charlotte" or the "Vessel") and Fouquet undertook to purchase the Vessel. A true and correct copy of the relevant pages of the Contract is attached hereto as Exhibit 1.
- 5. Pursuant to the Contract, Yardimci delivered the Vessel to Fouquet on or about March 2, 2006.

Fouquet's First Cause of Action for Breach of Warranty of the Reduction Gear

- 6. Pursuant to Article IX.1 of the contract, Yardimci guaranteed "all the propulsion equipments (main engine, reduction gear, shaft line and CPP) for a period of thirty-six (36) months as from the Actual Delivery Date. Any wear and tear within the design criteria will be for [Fouquet's] account after the first one year guarantee."
- 7. On May 23, 2008, while the Vessel was plying its trade on a voyage from Jorf Lasfar, Morocco to Bayonne, France, the Vessel suffered a breakdown of the reduction gear, more specifically, the gearbox ("Gearbox"), which forms part of the reduction gear. The reduction gear is a central part of the Vessel's propulsion system. As a result of the Gearbox

2

breakdown, the Vessel's main engine shut down so that the Vessel was without propulsion and adrift at sea. Accordingly, the Finisterre, Spain traffic control was contacted at 09:30 hours concerning the Vessel's breakdown and its location, at position 42° 19' N and 10° 52' W, which is 34 nautical miles south of the Finisterre traffic separation zone. As a result of the Gearbox breakdown, the Vessel was towed by the tug "Sting Ray" to the repair pier of the E.N.V.C. Ship Yard in Viana do Castelo, Portugal, which is the closest shippard in the area with an available pier.

- 8. Notification of the Vessel being adrift at sea, close to the Finisterre traffic separation zone, was vital because an adrift vessel can cause serious disruption and hazard to maritime commerce by interfering with vessels traversing the separation zone.
- 9. The breakdown of the Gearbox properly falls within the thirty-six month guarantee provided by Yardimci pursuant to Article IX.1 of the Contract.
- 10. Pursuant to Article IX.2 and Appendix 2 of the Contract, on May 29, 2008 Fouquet provided prompt notice of the Gearbox defect by way of e-mail, which included Article IX of the Contract for reference. A true and correct copy of the defect notice and attached Article IX is attached hereto as Exhibit 2.
- 11. As a result of the breakdown, Fouquet undertook to have three independent surveys of the Gearbox and the Vessel conducted. All three surveys determined that the cause of the gearbox failure was either a result of the original design of the Gearbox or the materials used in the construction of the Gearbox fitted on board the Vessel by Yardimci (both of which were the responsibility of Yardimci under the terms of the Contract) and that Fouquet's actions as owner did not contribute to the failure of the Gearbox. By way of example, a copy of the SCUA survey dated July 10, 2008 is annexed as Exhibit 3.

12. On or about July 10, 2008 Fouquet submitted to Yardimci the claim form regarding the Gearbox breakdown, demanding reimbursement "for the cost of the repairs." A true and correct copy of which is attached hereto as Exhibit 4.

Case 1:09-cv-07501-LAK

- 13. In order to prevent the Vessel from being placed off-hire for a lengthy period under the Vessel's charterparty and thus losing the revenue of the Vessel in maritime commerce, Fouquet undertook to make temporary repairs to the Gearbox at its own expense in accordance with Article IX.3, while awaiting new materials from the manufacturer to allow permanent repairs to be undertaken. As a result, pursuant to the Contract, Yardimci was required to immediately pay to Fouquet the costs of the repair.
- 14. In breach of the Contract, Yardimci has failed to reimburse Fouquet for expenses incurred to make the temporary repairs. Because of Yardimci's breach of the Contract, Fouquet has suffered damages in the amount of **US\$304,502.70** expended to make temporary repairs to the Gearbox.
- 15. After the temporary repairs were effected, Fouquet, again at its own expense and in accordance with Article IX.3, obtained new housing and new rotating gear wheels from the Gearbox manufacturer and made permanent repairs. As a result, again pursuant to the Contract, Yardimci was required to immediately pay to Fouquet the costs of the permanent repair. In breach of the Contract, Yardimci has failed to reimburse Fouquet for expenses incurred to make the permanent repairs. Because of Yardimci's breach of the Contract, Fouquet suffered damages in the amount of US\$2,649,344.71 expended to make the permanent repairs to the Gearbox.
- 16. A spread sheet providing a breakdown of the permanent repairs and the temporary repairs to the Gearbox, respectively, is attached hereto as Exhibit 5.

4

¹ The actual invoices for the numerous warranty repair items are voluminous, but are available and will be provided should the Court wish to review them.

Fouquet's Second Cause of Action for Breach of Warranty of Parts and Equipment

- 17. Pursuant to Article IX.1 of the Contract, entitled "Warranty of Quality", Yardimci guaranteed the Vessel for a period of twelve months following delivery to Fouquet for "hull and machinery and all parts, spare parts and equipment thereof that are manufactured or furnished or supplied by [Yardimci] and/or its subcontractors under this Contract including material, equipment ... against all defects which are due to defective materials, or equipment, errors, miscalculation, faulty construction, faulty design and/or poor workmanship."
- 18. Following delivery of the Vessel, numerous items on board the Vessel have required replacement and/or repair by reason of their being defective, faulty, of faulty design and/or poor workmanship.
- 19. Pursuant to Article IX.2 and Appendix 2, between June and November 2006, Fouquet provided prompt notices of defects for which claims are being submitted. True and correct copies of the notice letters are annexed as Exhibit 6.
- with Article IX.3. As a result, pursuant to the Contract, Yardimci was required to immediately pay to Fouquet the costs of the repair. In breach of the Contract, Yardimci has failed to reimburse Fouquet for expenses incurred to repair the warranty items. Because of Yardimci's breach of the Contract, Fouquet has suffered damages in the amount of US\$2,098,681.20 (that being the U.S. Dollar equivalent of Euro 1,499,058.00 with an exchange rate of Euro 1 US\$1.40) expended to make repairs to the warranty items. A spreadsheet setting forth a breakdown of the warranty claims is attached hereto as Exhibit 7.2

5

² The actual invoices for the numerous warranty repair items are voluminous, but are available and will be provided should the Court wish to review them.

21. By failing to remedy the defects alleged in paragraphs 6 to 20, Yardimci has breached the Contract. More specifically, Article XI.6 provides that " [Yardimci] shall be deemed to be in default under this Contract:....[if Yardimci] is in material breach relating to this Contract and fails to remedy same within ten (10) business days after [Fouquet's] notice....". As a result of Yardimci's breach, Fouquet has suffered damages in principal amount as follows:

Initial Repair to Gearbox	US\$ 304,520.70
Subsequent Surveys and Repairs to Gearbox	US\$2,649,344.71
Additional Warranty Items Total Principal Claim	US\$2,098,681.20 US\$5,052,546.61

- 22. On or about February 5, 2009, Fouquet sent a letter to Yardimci requesting settlement of the outstanding claims related to the breach of the warranty by Yardimci. A true and correct copy of the letter dated February 5, 2009 (without exhibits, many of which are already provided as exhibits herein), is annexed as Exhibit 8.
- 23. On or about February 27, 2009, London Solicitors Norton Rose LLP, acting on behalf of Fouquet, sent a letter to Yardimci requesting settlement of the outstanding warranty claims. A true and correct copy of the letter dated February 27, 2009 is annexed as Exhibit 9.
- 24. Under Article XIII.1 of the Contract, any and all disputes arising under the Contract are subject to arbitration in London under English Law.
- 25. Under English law, a valid maritime claim arises out of "construction, repair or equipment of any ship." Int'l Convention Relating to the Arrest of Sea-Going Ships art. 1(1)(1), May 10, 1952, 439 U.N.T.S. 193 (ratified by the United Kingdom on Mar. 18, 1959). Fouquet's breach of warranty claims under the Contract are valid maritime claims under English law and thus supports its Rule B application. See Sonito Shipping Co. Ltd. v. Sun United Maritime Ltd., 478 F. Supp. 2d 532, 536 (S.D.N.Y. 2007) ("[t]he existence vel non of a valid maritime claim for

purposes of a Rule B writ of attachment turns upon the applicable substantive law, in this case the law of contract."); see also Naias Marine S.A. v. Trans Pacific Carriers Co. Ltd., 2008 U.S. Dist. LEXIS 2438, at *10 (S.D.N.Y. Jan. 9, 2008) (holding that English law controlled whether plaintiff met its burden of showing that it has a maritime claim in support of a Rule B application by stating "the parties agreed that English law would govern under the charter party, thus, the Court considers whether Naias has asserted a maritime claim under English law."); Carpentine Limited v. Stocznia Szezecinska Nowa Sp. z.o.o., No. 09 Civ. 358 (GEL) (granting Order of Maritime Attachment and Garnishment for the breach of a vessel shipbuilding and sale contract subject to English law); but see Harley Mullion & Co. Limited v. Calverton Marine Limited, 2008 WI. 4905460 (S.D.N.Y. Aug. 7, 2008) (failing to apply the substantive law of the contract to the maritime claim consideration for Rule B purposes.).³

- 26. Under English law and in London arbitration, arbitration awards regularly include costs, including a reasonable allowance for attorneys' fees. Attorneys' fees and arbitration costs are estimated to be US\$400,000.00.
- 27. It is estimated that it will take approximately two (2) years to resolve this matter. Under relevant English law and arbitration procedure, a reasonable interest rate is 3.25%, resulting in the following estimated interest and attorneys' fees in addition to Fouquet's principal claim:

In the alternative, pursuant to Fed. R. Civ. P. 8(d)(2) and (3), the Court has admiralty jurisdiction under the general maritime law of the United States over the repair aspects of the Contract. See Kalafrana Shipping Ltd. v. Sea Gull Shipping Co. Ltd., 2008 WL 4489790, at *4 and n. 53, 54 (S.D.N.Y. Oct. 4, 2008) (holding admiralty jurisdiction exists with respect to the repair aspects of a ship sales contract, analogous to the Contract herein). Article IX, Warranty of Quality, provides Yardimci "further guarantees any repair or replacement effected pursuant to this Article." Exhibit I; see also IX.3, addressing equipment repairs. Certainly Fouquet is mindful of the general U.S. rule that shipbuilding contracts are not maritime (see, e.g., People's Ferry Co. v. Beers, 61 U.S. (20 How.) 393 (1857)), which would preclude the Rule B action here. However, the Vessel failure and claims did not occur during the Vessel construction period; the Vessel failures occurred after delivery while the Vessel was in navigable waters and performing maritime commerce activities. Stated differently, this is a claim based on failure to repair an identifiable vessel belonging to Fouquet, not a construction claim. As such, Fouquet's allegations must be construed "so as to do justice" and under whichever law applies to this Supplemental Rule B action, Plaintiff should be entitled to security in support of the underlying arbitration proceeding. Fed. R. Civ. P. 8(e).

Total Sought:	<u>SS:</u>	<u>5,780,962.14</u>
Principal Claim:		5,052,546.61
Attorneys' fees and costs	\$	400,000.00
Interest (3.25% on US\$5,052,546.61 for two years)	\$	328,415.53

- Article II.1 of the Contract provides for the contract price to be in U.S. Dollars, subject to an adjustment for the exchange rate of Euros. Article II.2 requires that all payments by Fouquet to Yardimci be made in U.S. Dollars. Article II.4 provides that payment should be remitted by "telegraphic transfer" to an account number nominated by Yardimci. It is common practice in the international shipbuilding industry for contracts to require that payments be made in U.S. Dollars and payments are made in U.S. Dollars in conformance with such requirements. "Telegraphic transfers" may be made by electronic fund transfers. International electronic fund transfers in U.S. Dollars between two non-U.S. entities pass through intermediary banks in New York.
- evidenced by the U.S. Dollar amounts included in the Contract—does have goods, chattels, credits, letters of credit, bills of lading, debts, effects and monies, funds, credits, wire transfers, accounts, letters of credit, electronic fund transfers, freights, sub-freights, charter hire, sub-charter hire, or other tangible or intangible property which belongs to it, is claimed by it, is being held for it or on its behalf, or which is being transferred for its benefit, within the jurisdiction at the following financial institutions: ABN Amro Bank; American Express Bank; Banco Popular; Bank of America, N.A.; Bank of China; Bank Leumi USA; The Bank of New York Mellon; Bank of Tokyo-Mitsubishi UFJ Ltd.; BNP Paribas; Calyon Investment Bank; Citibank, N.A.; Commerzbank; Deutsche Bank Trust Company Americas; HSBC Bank USA, N.A.; JPMorgan

Chase Bank, N.A.; Standard Chartered Bank; Société Générale; UBS AG; Wachovia Bank, N.A.; or other financial institutions within the Southern District of New York.

30. While all disputes arising out of the Contract are to be arbitrated in London, this action is submitted in accordance with Rule B of the Supplemental Rules of Admiralty and Maritime Claims of the Federal Rules of Civil Procedure as well as 9 U.S.C. §8 and should not be considered a waiver of the Contract's arbitration clauses.

WHEREFORE, Fouquet Sacop S.A. demands judgment as follows:

- 1. That process in due form of law according to the practice of this Court in the form of a writ of maritime attachment be issued against the Defendant Yarmimci Gemi Insa A.S. in the amount of US\$5,780,962.14 (including estimated interest, attorneys' fees and arbitration costs), and if Defendant Yardimci Gemi Insa A.S. cannot be found, then that its goods, chattels, credits, letters of credit, bills of lading, debts, effects and monies, funds, credits, wire transfers, accounts, letters of credit, electronic fund transfers, freights, sub-freights, charter hire, sub-charter hire, or other tangible or intangible property which belongs to it, is claimed by it, is being held for it or on its behalf, or which is being transferred for its benefit, within the district may be attached in an amount sufficient to answer Plaintiff's claim;
- 2. That Yardimci Gemi Insa A.S. and any other person claiming an interest therein may be cited to appear and answer the matters aforesaid;
- 3. That this court recognize and confirm any arbitration award(s) or judgment(s) rendered on the claims set forth herein as a Judgment of this Court, along with awarding Plaintiff's attorney's fees and costs in connecting with these actions;

- 4. That this Court retain jurisdiction over this matter through the entry of any judgment or award associated with any of the claims currently pending, or which may be initiated in the future, including any appeals thereof; and
- That this Court grant Plaintiff such other and further relief which it may deem just and proper.

Dated: New York, New York August 27, 2009

HOLLAND & KNIGHT LLP

By:

James H. Hohenstein Christopher R. Nolan Lissa D. Schaupp HOLLAND & KNIGHT LLP 195 Broadway New York, NY 10007-3189

(212) 513-3200

Telefax: (212) 385-9010

E-mail: jim.hohenstein@hklaw.com

chris.nolan@hklaw.com lissa.schaupp@hklaw.com

Attorneys for Plaintiff, Fouquet Sacop S.A.

VERIFICATION

STATE OF NEW YORK

:88.:

)

COUNTY OF NEW YORK

CHRISTOPHER R. NOLAN, being duly sworn, deposes and says:

I am associated with the firm of Holland & Knight LLP, counsel for Plaintiff Fouquet Sacop S.A. ("Plaintiff") in the foregoing action. I have read the foregoing Verified Complaint and know the contents thereof, and the same are true and correct to the best of my knowledge. I have reviewed documentation provided to me by Plaintiff and corresponded with Plaintiff's representatives regarding this matter. I am authorized by Plaintiff to make this verification, and the reason for my making it as opposed to an officer or director of Plaintiff is that there are none within the jurisdiction of this Honorable Court.

Christopher R. Nolan

Sworn to before me this 27th day of August, 2009

Notary Public

Anthony C. Keeney Notary Public, State of New York NO. 01KE6181777 Qualified in Westchester County Certificate Filed in New York County

8784184_v1

EXHIBIT 1

ACQUISITION CONTRACT

FOR

ONE 11,000 DWT MOLTEN SULPHUR AND ASPHALT TANKER

(HULL NO. 040)

BETWEEN

FOUQUET SACOP SA OR NOMINEE

AS BUYER

AND

YARDIMCI GEMI INSA A.S.

AS BUILDER

ACQUISITION CONTRACT V3 code26(Final Version)Final Version

sa vy

PAGE LOF LUPDATE 17

ARTICLE II

CONTRACT PRICE & TERMS OF PAYMENT

1 CONTRACT PRICE

The Contract Price of the VESSEL is United States Dollars Twenty Six Million Five Hundred Thousand (USD26.500,000), receivable by the BUILDER (hereinafter called the "Contract Price"), which is exclusive of the cost for the BUYER's supplies as provided in Article V hereof, and shall be subject to upward or downward adjustment, if any, as hereinafter set forth in this Contract.

The Contract Price of the Vessel is to be partly adjusted for an amount of United States Dollars Eight Million Five Hundred Thousand (USD8,500,000) which will remain the same up to a rate of exchange of US\$1.19/€1. Above this rate of exchange (however capped at US\$1.30/€1) the Buyer will compensate the Builder, at the time of delivery of the VESSEL upon the exchange rate US\$/€ then prevailing at such delivery date.

2 CURRENCY

Any and all payments by the BUYER to the BUILDER under this Contract shall be made in United States Dollars.

3 TERMS OF PAYMENT

The Contract Price shall be paid by the BUYER to the BUILDER in instalments as follows:

(a) 1st Instalment:

The sum of United States Dollars Two Million Six Hundred and Fifty Thousand (USD2,650,000), representing ten percent (10%) of the Contract Price shall become due and payable and be paid by the BUYER on steel cutting scheduled to take place on 18 June 2004 provided that the BUILDER has provided the BUYER with the following documents:

- Certificate issued by the Classification Society confirming the milestone is achieved;
- Refund guarantee and counter guarantee issued in compliance with Article II 5 hereunder.

(b) 2nd Instalment:

The sum of United States Dollars Three Million Nine Hundred and Seventy Five Thousand (USD3,975,000), representing fifteen percent (15%) of the Contract Price shall become due and payable and be paid by the BUYER on keel laying scheduled to take place on 30 August 2004 provided that the BUILDER has provided the BUYER with the following documents:

- Certificate issued by the Classification Society confirming the milestone is achieved:
- Refund guarantee and counter guarantee issued in compliance with Article II 5 hereunder.

(c) 3rd Instalment:

The sum of United States Dollars Two Million Six Hundred and Fifty Thousand (USD2,650,000), representing ten percent (10%) of the Contract Price shall become due and payable and be paid by the BUYER on delivery of the main engine scheduled to take place on 15 November 2004 provided that the BUILDER has provided the BUYER with the following documents:

Certificate issued by the Classification Society confirming the milestone is achieved;

Refund guarantee and counter guarantee issued in compliance with Article II - 5 hereunder.

(d) 4th Instalment:

The sum of United States Dollars Three Million Nine Hundred and Seventy Five Thousand (USD3.975.000), representing fifteen percent (15%) of the Contract Price shall become due and payable and be paid by the BUYER on launching of the Vessel scheduled to take place on 1st February 2005 provided that the BUILDER has provided the BUYER with the following documents:

- Certificate issued by the Classification Society confirming the milestone is achieved;
- Refund guarantee and counter guarantee issued in compliance with Article II 5 hereunder.

(e) 5th Instalment

The sum of United States Dollars Thirteen Million Two Hundred and Fifty Thousand (USD13,250,000), representing fifty percent (50%) of the Contract Price, plus any increase or minus any decrease due to modification and/or adjustment of the Contract Price, if any, in accordance with the provisions of this Contract, shall become due and payable on delivery of the VESSEL as evidenced by the execution by the BUILDER and the BUYER of the Protocol of Delivery and Acceptance mentioned in Article VII Delivery of this Contract.

4 METHOD OF PAYMENT

The BUYER shall remit the amount of the first and/or second and/or third and/or fourth instalments in accordance with Article II, Paragraph 3(a), 3(b), 3(c) or 3(d) by telegraphic transfer to the account number and bank to be nominated by BUILDER with instructions as follows: Payment for hull No 040 for Yardimci Gemi Insa A.S. or through other receiving bank to be nominated by the BUILDER from time to time and such nomination shall be notified to the BUYER at least ten (10) days prior to the due date for the payment.

5 REFUND GUARANTEE AND COUNTER GUARANTEE

As security for the BUILDER's obligations to refund to the BUYER each of the instalments received in accordance with sub-article 3(a) to 3(d) hereinabove, the BUILDER shall furnish to the BUYER a refund security by way of a refund guarantee substantially in the form attached in Appendix 3 hereto to be issued in favour of the BUYER by a bank satisfactory to the BUYER, such bank being Finansbank or such other Turkish bank, securing the due and punctual fulfilment of the said obligations. Such refund guarantee to be in an amount corresponding to the instalment to be paid and to be provided not later than three (3) banking days prior payment of the said instalment by the BUILDER's bank to the BUYER's bank by tested telex.

Such refund guarantee to be counter-guaranteed by a first class European bank to be acceptable to the BUYER and such counter guarantee to be in an amount corresponding to the amount guaranteed by the refund guarantee and to be provided not later than three (3) banking days prior payment of the said instalment by the BUILDER's bank to the BUYER's bank by tested telex.

Odni by

ARTICLE IX

Document 1

WARRANTY OF QUALITY

1 GUARANTEE OF MATERIAL AND WORKMANSHIP

The BUILDER, for a period of twelve (12) months following delivery to the BUYER of the VESSEL (the "Guarantee Period"), guarantees the VESSEL, her hull and machinery and all parts, spare parts and equipment thereof that are manufactured or furnished or supplied by the BUILDER and/or its subcontractors under this Contract including material, equipment (however excluding any parts for the VESSEL which have been supplied by or on behalf of the BUYER) against all defects which are due to defective materials, or equipment, errors, miscalculation, faulty construction, faulty design and/or poor workmanship.

As above mentioned, the BUILDER's guarantee shall not apply to the equipment supplied by the BUYER according to the Specifications, except to the extent of the installation which has been performed by the BUILDER.

The BUILDER shall assign to the BUYER to the extent assignable, concurrently with delivery and acceptance of the VESSEL all of its rights against any subcontractors and suppliers under any guarantee or warranty as security for its fulfilment of its obligations under this Article and notify the relevant supplier thereof. For so long as the BUILDER shall perform its obligations under this Article, the BUYER shall not exercise any of its rights under this assignment or under the assigned guarantees or warranties. Any assignment shall not limit the obligations of the BUILDER under this Contract. The BUILDER shall use its reasonable endeavours to negotiate rights of assignment in favour of the BUYER in respect of contracts entered into with suppliers or subcontractors.

All claims under guarantees or warranties assigned, wholly or partly according to this paragraph shall, if the BUYER so requests, and subject to the preceding paragraph, be made by the BUILDER on behalf of the BUYER.

To the extent that any guarantee or warranty of any subcontractor or supplier is broader or has a longer duration than the obligations of the BUILDER under this article, the BUILDER shall assign the benefit of such guarantee or warranty to the BUYER.

The BUILDER further guarantees any repair or replacement effected pursuant to this Article of such repair or replacement to the extent same is obtainable from the suppliers or manufacturers of the said equipment.

Pending agreement with the suppliers and/or manufacturers, the BUILDER's guarantee shall include:

all the propulsion equipments (main engine, reduction gear,) shaft line and CPP) for a period of thirty (36) months as from the Actual Delivery Date. Any wear and tear within the design criteria will be for the BUYER's account after the first one year guarantee.

The main diesel generators (auxiliary diesels generators, alternators and attached equipments. Any wear and tear within the design criteria will be for the BUYER's account after the first one year guarantee

UPDATED 17.12.2003

ACQUISITION CONTRACT V3 CODEZ6(FINAL VERSION)PAGE 29 OF 33

Level

Pending agreement with the suppliers and/or manufacturers, the BUILDER's guarantee shall include the paint coating of seawater ballast tanks and void spaces of the SHIP for a period of thirty six (36) months after the Actual Delivery Date under following terms and conditions:

(i)	Photo	1st year	RE 2
` .	(European scale	2nd year	RE 2
	degree of corrosion)	3rd year	RE 2

(ii)	Cover (costs)	1st year	100 %
	• •	2nd year	90 %
		3rd year	80 %

(iii)	Exclusion (areas)	1st year	1 %
,	. ,	2nd year	1,5 %
		3rd year	2 %

The BUYER shall not be obliged to carry out paint touch-ups or repairs during the Guarantee Period of thirty six (36) months if the condition of the paint remains within the above mentioned criteria.

All travelling, accommodation and incidental costs of the BUILDER and/or his Sub-Contractors and/or attending engineers shall be for the account of the BUILDER and his sub-contractors.

NOTICE OF DEFECTS 2

- (a) The BUYER shall notify the BUILDER by telefax or email, as promptly as possible, after discovery of any defect or deviations for which a claim is made under this guarantee. The BUYER's written notice (as per proforma attached hereto in Appendix 2) shall describe the nature of the defect and the extent of the damage caused thereby.
- (b) The BUILDER shall have no obligation under this guarantee for any defects discovered prior to the expiry date of the guarantee, unless notice of such defects, is given by the BUYER not later than fifteen (15) business days after such expiry date. Telefaxed or email advice with brief details explaining the nature of such defect and extent of damage is to be provided within fifteen (15) business days after such expiry date and a statement that a claim is forthcoming will be sufficient compliance with the requirements as to time.
- (c) The BUILDER is to acknowledge receipt of the claim by email or telefax within five three (3) days after notification sent by the BUYER by fax or email (such period will not apply when the defect or deficiency imperilled the VESSEL or her operations safety). The BUILDER within ten days of BUYER's request is to inform the BUYER as to whether the BUILDER accepts the claim to be covered by the Guarantee. If the BUILDER fails to respond within the ten day period, the BUILDER's acceptance shall be deemed granted.
- (d) If the BUILDER becomes aware of defective materials or design or construction within the nature of serial defect in respect of the VESSEL or any other vessel built by the BUILDER the BUILDER shall immediately notify the BUYER in writing and by telefax.

UPDATED 17.12.2003

(e) Any claim by the BUYER under this guarantee which is not accepted by the BUILDER shall, if possible as to content, be referred to the Classification Society for final decision and otherwise be referred to arbitration as provided for in Article XIII.

Document 1

REMEDY OF DEFECTS 3

The BUILDER shall remedy at its expense any defects, against which the VESSEL or any part of the equipment thereof is guaranteed under this Article by making all necessary repairs and/or replacement. Such repairs and/or replacement will be made by the BUILDER.

Drydocking if necessary including dry docking charges shall be for the account of the BUILDER to the extent that such dry-docking is proved to have been necessary in order to remedy any such defect; the burden of proof shall be borne by the BUYER in conjunction with the Classification Society.

Any freight or forwarding costs incurred by the BUILDER in respect of sending any spare parts or replacement parts to the VESSEL shall be for the account of the BUILDER.

However, if it is impractical to make the repair by the BUILDER, and if forwarding by the BUILDER of replacement parts, and materials can not be accomplished without impairing or delaying the operation or working of the VESSEL, then, in any such event, the BUYER shall cause the necessary repairs or replacements to be made elsewhere at the discretion of the BUYER provided that the BUYER shall first and in all events, as soon as possible, give the BUILDER notice by email confirmed by telefax of the time and place such repairs will be made, and the BUILDER shall have the right at its own cost to make attendance and verification without unreasonably impairing vessel's operational commitments by its own representative(s) or that of Classification Society of the nature and extent of the defects complained of. In all minor cases, the Guarantee Engineer, as hereinafter provided for, will act for and on behalf of the BUILDER.

In any circumstances, the BUILDER shall immediately pay to the BUYER by telegraphic transfer the actual cost for such repair or replacements including forwarding charges, or at the average costs of making similar repairs as quoted by three reputable shipyards or repair yards in Turkey, Spain, and Portugal.

EXTENT OF THE BUILDER'S LIABILITY


The BUILDER shall have no obligation and/or liabilities with respect to defects discovered after the expiration of the period of guarantee specified above except for the propulsion system, main diesel generators, painting system as mentioned in Article IX -1 the guarantee of which shall be for 36 months as from the Actual Delivery Date of the VESSEL.

The BUILDER shall be liable to the BUYER for defects and damages caused by any of the defects specified in Paragraph 1 of this Article provided that such liability of the BUILDER shall be limited to damage occasioned within the guarantee period specified in Paragraph 1 above. The BUILDER shall not be obligated to repair, or to be liable for, damages to the VESSEL, or to any part of the equipment thereof, due to ordinary wear and tear or caused by the defects other than those specified in Paragraph 1 above, nor shall there be any BUILDER's liability hereunder for defects in the VESSEL, or any part of the equipment thereof, caused by fire or accidents at sea or elsewhere, or mismanagement, misoperation, negligence, or wilful neglect, on the part of the BUYER, its employees or agents including the VESSEL's officers, crew and passengers, or any persons on or doing work on the VESSEL other than the BUILDER, its employees, agents or sub contractors.

UPDATED 17.12.2003

Likewise, the BUILDER shall not be liable for defects in the VESSEL, or the equipment or any part thereof, due to repairs or replacement which were made by those other than the BUILDER and/or their subcontractors without prior consent of the BUILDER, such consent to be deemed granted if the BUILDER fails to respond within the period mentioned in paragraph 2(c) of this Article.

Upon delivery and acceptance of the VESSEL in accordance with the terms of this Contract, the BUILDER shall thereby and thereupon be released of all responsibility and liability whatsoever and howsoever arising under or by virtue of this Contract (save in respect of those obligations to the BUYER expressly provided for in this Article IX). The BUILDER shall not, in any circumstances, be liable for any consequential loss or special loss, or expenses arising from any cause whatsoever including, without limitation, loss of time, loss of profit or earnings or demurrage directly from any commitments of the BUYER in connection with the VESSEL.



GUARANTEE ENGINEER 5

There will be a guarantee engineer (treated as a chief engineer) on a permanent basis for the first 3 months of the Guarantee Period.

The guarantee engineer will come back on board when deemed necessary upon request by the BUYER and at least the last month of the Guarantee Period.

Review of all guarantee claims will be done by meeting at Buyers office at the end of the Guarantee Period.

The costs of the guarantee engineer shall be borne by the BUIDER including repatriation costs; the BUYER shall provide the Guarantee Engineer with officer's class accommodations and facilities on board the VESSEL.

The BUILDER shall be responsible, at its costs and expenses for the PANDI liability of the guarantee engineer.

UPDATED 17.12,2003

ARTICLE XHI

DISPUTES AND ARBITRATION

1 PROCEEDINGS

In the event of any dispute between the parties hereto as to any matter arising out of or relating to this Contract or any stipulation herein or with respect thereto which cannot be settled by the parties themselves, such dispute shall be resolved by arbitration in London, England in accordance with the Laws of England as per rules of London Arbitration Act 1950 and 1979 or any statutory modifications or re-enactments for time being in force. The arbitration shall be arbitration with reasoned awards. Either party may demand arbitration of any such disputes by giving written notice to the other party. Any demand for arbitration by either party hereto shall state the name of the arbitrator appointed by such party and shall also state specifically the question or questions as to which such party is demanding arbitration. Within ten (10) business days after receipt of notice of such demand for arbitration, the other party shall in turn appoint a second arbitrator. The two arbitrators thus appointed shall thereupon select a third arbitrator, and the three arbitrators so named shall constitute the board of arbitration (hereinafter called the "Arbitration Board") for the settlement of such dispute.

In the event however, that said other party should fail to appoint a second arbitrator as aforesaid within ten (10) business days following receipt of notice of demand of arbitration, it is agreed that such party shall thereby be deemed to have accepted and appointed as its own arbitrator the one already appointed by the party demanding arbitration, and the arbitration shall proceed forthwith before this sole arbitrator, who alone, in such event, shall constitute the Arbitration Board. And in the further event that the two arbitrators appointed respectively by the parties hereto as aforesaid should be unable to reach agreement on the appointment of the third arbitrator within ten (10) business days from the date on which the second arbitrator is appointed, either party of the said two arbitrators may apply the President of the London Maritime Arbitrators' Association in London to appoint the third arbitrator. The award of the arbitration, made by the sole arbitrator or by the majority of the three arbitrators as the case may be, unless appealed by either party, shall be final, conclusive and binding upon the parties hereto:

2 ALTERNATIVE ARBITRATION BY AGREEMENT

Notwithstanding the preceding provisions of this Article, it is recognized that in the event of any dispute or difference of opinion arising in regard to technical matters on the construction of the VESSEL, her machinery and equipment, or concerning the quality of materials or workmanship in relation to class matters thereof or thereon, such dispute shall be referred to the Classification Society. In such case, the opinion of the Classification Society shall be final and binding on the parties hereto.

3 NOTICE OF AWARD

Notice of any award shall immediately be given in writing or by telefax confirmed in writing to the BUILDER and the BUYER.

IK

4 EXPENSES

The arbitrator(s) shall determine which party shall bear the expenses of the arbitration or the proportion of such expenses which each party shall bear.

5 AWARD OF ARBITRATION

Award of arbitration, unless appealed by either parties, shall be final and binding upon the parties concerned.

6 ENTRY IN COURT

Judgement on any award may be entered in any court of competent jurisdiction.

7 ALTERATION OF DELIVERY TIME

In the event of reference to arbitration of any dispute arising out of matters occurring prior to delivery of the VESSEL, the BUILDER shall not be entitled to extend the Delivery Date as defined in Article VII hereof and the BUYER shall not be entitled to postpone its acceptance of the VESSEL on the Delivery Date or on such newly planned time of delivery of the VESSEL as declared by the BUILDER. However, if the construction of the VESSEL is affected by any arbitration or court proceeding, the BUILDER shall then be permitted to extend the Delivery Date as defined in Article VII and the decision or the award shall include a finding as to what extent the BUILDER shall be permitted to extend the Delivery Date.

Daye

UPDATED 17.12.2003 4

APPENDIX 2

DEFECTS PICKUP LIST N°

DATE ISSUED		LEVEL: NORMAL HIGH URGENT GUARANTEE: YES	
DEPARTMENT EQUIPMENT: TYPE: MAKER: DRAWING No:	:	OWNER CODE:	
Article L	DEFECT DESCRIPTION		
Article II.	REPAIR WORKS OR INVESTIGATION	ON CARRIED OUT	
Article III.	SPARE PARTS OR MATERIALS USI	ED	
Article IV.	REQUIRED ACTION		
REQUIRED SPA	ARE PARTS		
Article V.	COMMENTS		
Article VI. Officers Rating	VESSEL 'S SERVICES Normal hour	overtime	
CONTRACTOR	IS USED by managers due to emergency	situation].
EMERGENCY	SITUATION DUE TO:		T SK
Contractors:		cost estimates;	SK

ACQUISITION CONTRACT V3 CODE26(FINAL VERSION)PAGE 52 OF 56

UPDATED 17.12.2003

EXHIBIT 2

From:

FIEVET Frédéric [IMCEAEX-

_O=FSM_OU=EXCHANGE+20ADMINISTRATIVE+20GROUP+20+28FYDIBOHF23SPDLT+29_CN=RECIPIENTS_CN=FFIEVET@sea-

tankers.fr

Sent

Thursday, May 29, 2008 11:58 AM

To:

Hasan Koray Coskun

Cc:

Huseyin YARDIMCI; Guarantee DEPARTMENT; Ugur SOKU; GARIN Christian; CUZZI Florence; MASSOT Alain

Subject:

RE: 'Contracts' for MAK 6M43 Marine Diesel Engine Including Propulsion Packace

Attachments: _0529174328_001.tif

Good evening

Thank you for your mail.

It confirms initial terms between FS & Yardimci (cf attached pages)

As mentioned by phone to Huseyin, FS CHARLOTTE suffered gear box defect on 23/05, 50 Miles off Vigo. Decision was made to tow the vessel to Viana do Castelo, ENVC ship Yard, Portugal FS CHARLOTTE berthed at ship yard on 26/05

Survey by SCANA VOLDA technician is in progress started 26/05:

- full dismantling
- full disembarking
- transportation tomorrow to Norway for full survey, expected to start 3/06/2008 in SCANA VOLDA factory

Kindly inform NIVEKO accordingly

- To liaise with SCANA VOLDA
- > And confirm guarantee coverage of such failure

For any technical detail you may contact Alain MASSOT 33 6 20 51 25 22 / technical@fsm.fr

Waiting for hearing from you

Best regards



Frédéric FIEVET Fleet Manager

Phone: 00 33 (0)4 95 09 31 43 Mobile: 00 33 (0)6 13 07 95 39

Fax: 00 33 (0)4 95 09 31 39 Mailto: filevet@fsm.fr



De: Hasan Koray Coskun [mailto:koraycoskun@yardimci.gen.tr]

Envoyé: jeudi 29 mai 2008 16:15

A : FIEVET Frédéric

Cc: Guarantee DEPARTMENT; Ugur SOKU

Objet: 'Contracts' for MAK 6M43 Marine Diesel Engine Including Propulsion Packace

Good afternoon Mr. Fievet.

Please find attached 'Contract' for MAK 6M43 Marine Diesel Engine Including Propulsion Packace drafted on 17.04.2004 and Main Engine Warranty Extension Contract (addendum to 17.04.2004 contract) dated on August 2004 between Niveko (Mak) and Yardımcı Shipyard.

Thope we can help.

Best Regards,

H. Koray COSKUN - Marine Chief Engineer

Guarantee Department Manager YARDIMCI SHIPYARD Tersaneler Cad. 50. Sok. No:7 34947 Tuzla Istanbul TURKIYE # [+90] (216) 493 80 00 - (250) # [+90] (216) 493 02 26 Mobile: [+90] (533) 6596219 Koraycoskun@yardimci.gen.tr guaranteedepartment@yardimci.gen.tr

ARTÍCLE IX

WARRANTY OF QUALITY

GUARANTEE OF MATERIAL AND WORKMANSHIP 1

The BUILDER, for a period of twelve (12) months following delivery to the BUYER of the VESSEL (the "Guarantee Period"), guarantees the VESSEL, her hull and machinery and all parts, spare parts and equipment thereof that are manufactured or furnished or supplied by the BUILDER and/or its subcontractors under this Contract including material, equipment (however excluding any parts for the VESSEL which have been supplied by or on behalf of the BUYER) against all defects which are due to defective materials, or equipment, errors, miscalculation, faulty construction, faulty design and/or poor workmanship.

As above mentioned, the BUILDER's guarantee shall not apply to the equipment supplied by the BUYER according to the Specifications, except to the extent of the installation which has been performed by the BUILDER.

The BUILDER shall assign to the BUYER to the extent assignable, concurrently with delivery and acceptance of the VESSEL all of its rights against any subcontractors and suppliers under any guarantee or warranty as security for its fulfilment of its obligations under this Article and notify the relevant supplier thereof. For so long as the BUILDER shall perform its obligations under this Article, the BUYER shall not exercise any of its rights under this assignment or under the assigned guarantees or warranties. Any assignment shall not limit the obligations of the BUILDER under this Contract. The BUILDER shall use its reasonable endeavours to negotiate rights of assignment in favour of the BUYER in respect of contracts entered into with suppliers or subcontractors.

All claims under guarantees or warranties assigned, wholly or partly according to this paragraph shall, if the BUYER so requests, and subject to the preceding paragraph, be made by the BUILDER on behalf of the BUYER.

To the extent that any guarantee or warranty of any subcontractor or supplier is broader or has a longer duration than the obligations of the BUILDER under this article, the BUILDER shall assign the benefit of such guarantee or warranty to the BUYER.

The BUILDER further guarantees any repair or replacement effected pursuant to this Article of such repair or replacement to the extent same is obtainable from the suppliers or manufacturers of the said equipment.

Pending agreement with the suppliers and/or manufacturers, the BUILDER's guarantee shall include:

- all the propulsion equipments (main engine, reduction gear, shaft line and CPP) for a period of thirty (36) months as from the Actual Delivery Date. Any wear and tear within the design criteria will be for the BUYER's account after the first one year guarantee.
- The main diesel generators (auxiliary diesels generators, alternators and attached equipments. Any wear and tear within the design criteria will be for the BUYER's account after the first one year guarantee Jul

UPDATED 17.12.2003

1K

Pending agreement with the suppliers and/or manufacturers, the BUILDER's guarantee shall include the paint coating of seawater ballast tanks and void spaces of the SHIP for a period of thirty six (36) months after the Actual Delivery Date under following terms and conditions:

(i)	Photo (European scale degree of corrosion)	1st year 2nd year 3rd year	RE 2 RE 2 RE 2	
(ii)	Cover (costs) 1st your 2nd y 3rd y	/ear	100 % 90 % 80 %	
(iii)	Exclusion (areas)	1st year 2nd year 3rd year		1 % 1,5 % 2 %

The BUYER shall not be obliged to carry out paint touch-ups or repairs during the Guarantee Period of thirty six (36) months if the condition of the paint remains within the above mentioned criteria.

All travelling, accommodation and incidental costs of the BUILDER and/or his Sub-Contractors and/or attending engineers shall be for the account of the BUILDER and his sub-contractors.

NOTICE OF DEFECTS 2

- (a) The BUYER shall notify the BUILDER by telefax or email, as promptly as possible, after discovery of any defect or deviations for which a claim is made under this guarantee. The BUYER's written notice (as per proforma attached hereto in Appendix 2) shall describe the nature of the defect and the extent of the damage caused thereby.
- (b) The BUILDER shall have no obligation under this guarantee for any defects discovered prior to the expiry date of the guarantee, unless notice of such defects, is given by the BUYER not later than fifteen (15) business days after such expiry date. Telefaxed or email advice with brief details explaining the nature of such defect and extent of damage is to be provided within fifteen (15) business days after such expiry date and a statement that a claim is forthcoming will be sufficient compliance with the requirements as to time.
- (c) The BUILDER is to acknowledge receipt of the claim by email or telefax within five three (3) days after notification sent by the BUYER by fax or email (such period will not apply when the defect or deficiency imperilled the VESSEL or her operations safety). The BUILDER within tendays of BUYER's request is to inform the BUYER as to whether the BUILDER accepts the claim to be covered by the Guarantee. If the BUILDER fails to respond within the ten day period, the BUILDER's acceptance shall be deemed granted.
- (d) If the BUILDER becomes aware of defective materials or design or construction within the nature of serial defect in respect of the VESSEL or any other vessel built by the BUILDER the BUILDER shall immediately notify the BUYER in writing and by telefax.

There

1K

EXHIBIT 3

10th July 2008

L 038/08 JN/LIZ Ref.No.:


PRELIMINARY SURVEY REPORT

M/V "FS CHARLOTTE" of Marseille

9.416 tons. gross.

2006 Built year:

Master: J.D. Le Merrer



At the request of SCUA Antwerp NV and on behalf of the Leading Hull Underwriters, the undersigned South Europe SCUA Office Lda. at Alcoitão has on the 26th May 2008 and subsequent days surveyed the above mentioned vessel, without prejudice to liability, whilst lying alongside the repair berth at E.N.V.C. Shipyard, Viana do Castelo, Portugal.

-2-

"FS CHARLOTTE"

Present at the survey were also:	Representing:
Mr, J.D. Le Merrer, Master	The Owners
Mr. A. Derrien, Chief Engineer	The Owners
Mr. A. Massot, Technical Manager	The Owners
Mr. B. Minguet,	The Charterers, TOTAL
Mr. K.I. Øye, Service Engineer	Scana Volda
Mr. S. Aarflot, Service Engineer	Scana Volda
Mr. P. Neiva, Ship Manager	The E.N.V.C. Shipyard

The vessel departed from Jorf Lasfar, Morocco in ballast,			
bound for Bayonne, France	21st	May	2008
Main engine reduction gear box troubles first experienced			
under passage	23rd	May	2008
Damage sustained to the main engine reduction gear box	23rd	May	2008
Tug "STING RAY" made fast and started towing			
towards Viana do Castelo	23rd	May	2008
Vessel arrived at Viana do Castelo anchorage and tug			
"STING RAY" released	24th	May	2008
The vessel shifted alongside the E.N.V.C. repair berth	24th	May	2008
Repairs commenced	26th	May	2008
Main reduction gear box dismantled	29th	May	2008
Main reduction gear box arrived at Scana Volda in			
Norway	13th	June	2008

Survey was held in order to ascertain the nature and extent of damage sustained on the following occasion:

~3~

<u>"FS CHARLOTTE"</u>

OCCURRENCE

23rd May 2008

On voyage from Jorf Lasfar, Morocco to Baionne, France in ballast. Main engine reduction gear box troubles

Information available:

Statement of the Master, as per enclosure no.1.

Chief Engineer's Damage Report, as per enclosure no.2

GENERAL INFORMATION

The "FS CHARLOTTE" is a molten sulphur/asphalt tanker with a Dead Weight of 12.496 tonnes, having been built at Yardmici Tersanesi A.S. in Tusla, Turkey in 2006, as yard no. 40.

The propulsion is provided by one 4-stroke MaK diesel engine, type 6M43, having 6 cylinders in line with 430 mm. bore and 610 mm. stroke, developing 5.400 kW. at 500 r.p.m., driving a 4 bladed controllable pitch propeller through a reduction gear box make: Scana Volda, type ACG105/850K/PF680-1 with the serial no. 1556.

This reduction gear box is provided with a power take off, driving an AVK DSU 86 shaft alternator, generating 1490 kW at 1800 r.p.m. that can also be used for propulsion in emergency situations (PTO/PTI).

The reduction gear box is a single-stage step up gear, with helical toothed, case hardened and flank ground gear wheels, built into a housing of cast iron.

The reduction gear ratio applied to the propulsion shaft is 3,58:1 and a hydraulic clutch make: Ortlinghaus type 85.000 is fitted on the forward end of the input shaft.

The PTO shaft is engaged through a hydraulic clutch make: Ortlinghaus type 69.001.

The input and propulsion shafts are bedded in pressure oil lubricated bearings lined with white metal, whereas the PTO shaft is supported by roller bearings make: NACHI, Japan.

Alcoitão

"FS CHARLOTTE"

OCCURRENCE (cont.)

The gear box lubrication oil system is common with the controllable pitch propeller lubrication oil system.

The normal lubrication oil pressure of the reduction gear box according to the maker's instruction manual is 4 bar and the main lub oil pump with a capacity of 202 lts/min at 1800 rpm is driven by the PTO shaft while also an electrically driven stand-by lubrication oil pump is also provided.

The set point for the gear box low lubrication oil pressure alarm is 1.5 bar and for the main engine shutdown by gear box extra low lube oil pressure is 1.0 bar.

The Bureau Veritas inspection certificate of the reduction gear box was issued on 22.02.05 with the design review having been carried out on 21.09.04 and the gear box last inspected at the manufacturer premises on 20.10.04.

The data sheet for sea trials from Scana Volda found on board, though not signed nor stamped, indicates that first function test of the lubrication oil pump prior to sea trials was carried out on 29.01.06 and the sea trials having been commenced on 30.01.06 and completed on 02.02.2006. Also according with the same Scana Volda data sheet for sea trials, the gear contact patterns of both the propulsion and PTO gears were apparently not verified after sea trials.

The gear box had 14.800 running hours until the casualty date and the on board maintenance control is computer based, using the PMS Version 1.25 software.

The last routine maintenance tasks performed on the reduction gear box were reportedly the checking of the stop function control on 08.05.08 and the checking of the suction filter of the lubrication oil system carried out on 07.05.08 without any remarks.

It was also stated that no intervention besides normal maintenance routines had been carried out on the gear box.

The latest lubrication oil analysis report found onboard was dated 11.03.08, having been issued by TOTAL Lubrarine and confirming the oil in good condition.

It should however be noted that the Fe content had increased steadily from 15 mg/kg on February 2007 to 28 mg/kg on March 2008, indicating the occurrence and increase of wear in the gear box.

"FS CHARLOTTE"

OCCURRENCE (cont.)

NARRATIVE

According to the information submitted by the Master and the Chief Engineer, as well as the one contained on the vessel's Deck and Engine Log Book copies and in the Chief Engineer's and Master's Damage reports, the vessel departed from Jorf Lasfar, Morocco on 21.05.08 in ballast, bound for Bayonne, France.

On 23.05.08 at 02:14 hrs, with the vessel under passage and the engine room unattended and the electrical power supplied by the shaft alternator, the C.P. propeller low lube oil pressure alarm went off with the pressure at 1.3 bar, followed by an automatic stop of the main engine, causing a black out.

At 02:15 hrs the electrical power was re established by the standby diesel generator.

After the installation had been checked by the crew, the main engine was restarted at 02:25 hrs with the C.P.P. lube oil pressure reportedly verified at 3.8 bar and the passage was resumed by 02:45 hrs with the shaft alternator disengaged, allegedly as precaution with and the electrical power supplied by the no.3 diesel engine driven generator.

Upon several hours with all reduction gear parameters reportedly verified to be normal by the engine crew, namely the lube oil pressure at 3.8 bar in the engine control console and at 4.4 bar locally, the shaft alternator was engaged again at 09:05 hrs in the morning.

At 09:23 hrs the C.P.P. low lube oil pressure alarm went off again reportedly with the oil pressure at 1 bar, whereupon the stand-by reduction gear lub. oil pump was manually started with the oil pressure reaching 4 bar.

Subsequently the no.3 diesel generator was re-connected to the main switchboard and the shaft alternator disengaged.

A few minutes later at 09:27 hrs the stand by lubrication oil pump was stopped and the lube oil pressure was immediately noticed reducing with the C.P.P. low lube oil pressure alarm coming off again and the main engine shutting down, although the stand by pump had been meanwhile re-started.

The Finisterre traffic control was contacted at 09:30 hrs with the vessel being declared not under command at position 42° 19' N and 10° 52' W, 34 NM south of the Finisterre traffic separation zone.

-6·

"FS CHARLOTTE"

OCCURRENCE (cont.)

Further checking of the propulsion installation was carried out without finding any abnormality, whereupon the main engine was re-started again at 09:35 hrs, but was immediately manually stopped thereafter after a loud noise noticed coming from the reduction gear which housing was later found holed and cracked.

Upon opening the inspection door both forward roller bearings of the PTO shaft were observed to be severely damaged and with roller elements missing.

Whilst the vessel being adrift the management company was contacted to arrange a tugboat and at 14:20 hrs the first VHF contact was established with the tug "STING RAY" having arrived at the scene at 15:30 hrs and started towing the vessel towards Viana do Castelo at 16:33 hrs, where the tow arrived on 24.05.08 at 14:20 hrs.

The tug "STING RAY" was released at 18:36 hrs the same day, whereupon the vessel was shifted alongside the E.N.V.C. repair pier by 19:50 hrs.

INSPECTION AT VIANA DO CASTELO

We firstly attended on board on 26.05.08 and noticed that two service engineers from Scana Volda had started dismantling the reduction gear box on the same day.




Photo 1: Reduction gear box with holed housing

The gear housing its upper casing was found holed and cracked in its lower casing in way of the PTO gear wheel.

"FS CHARLOTTE"

OCCURRENCE (cont.)

The attached lubrication oil pump was verified rotating freely and in apparent good condition with the shaft key in place, albeit with the synthetic coupling element found distorted.

Through the inspection doors in the gear box housing it was possible to observe the PTO wheel, which showed two teeth partly broken off and several other teeth battered.

The propulsion shaft was verified in place by the service engineers by using a dial gauge and its alignment was allegedly found in satisfactory condition.

An access opening had to be cut in the starboard side shell above the main deck in way of the engine room in order to land the dismantled gear box parts ashore.

On 29.05.08 the dismantling was completed when the PTO shaft assembly was inspected at the E.N.V.C. workshop, revealing that both forward roller bearings were significantly damaged with the retaining side rings and several roller elements missing and that the PTO shaft in between the forward roller bearing and the pinion was heavily grooved

The aft roller bearing on the PTO shaft was found with only the side retaining ring affected.

The following marking was found on the roller bearings: NACHI 22232E W33C3 P1 **JAPAN**




Photo 2: PTO pinion and roller bearings with loose roller elements

"FS CHARLOTTE"

OCCURRENCE (cont.)

Upon completion of the dismantling the damages observed in the pinion/wheel sets were as follows:

- Main propulsion pinion with 3 partly broken out teeth and several other battered;
- Main propulsion wheel with 2 teeth partly broken out and one heavily battered;
- PTO pinion with light scoring marks only;
- PTO wheel with several teeth partly broken out;

The PTO clutch was found with metallic particles inside.



Photo 3: Severe grooving and battering marks on the PTO shaft and loose roller element

The dismantled gear box was sent by truck to Scana Volda in Aalesund, Norway for a complete assessment of its condition, having arrived there on 13.06.08, whereupon it was concluded that a new housing and new rotating gears wheels would have to be provided and additionally all 4 white metal bearings and 3 roller bearings.

Given the 6 month delivery time foreseen by manufacturers, a temporary solution was proposed by the Owners and agreed upon with Scana Volda, comprising the repair of the affected propulsion pinion and wheel by cutting the affected teeth short in order to remove the affected areas.

"FS CHARLOTTE"

OCCURRENCE (cont.)

The repaired gear wheels would be fitted into a new gear housing available at Scana Volda and the maximum acceptable load on the gear box would have to be temporarily reduced to 3900 kW, while the PTO shaft would not be fitted.

An independently driven lubrication oil pump would have also to be fitted and fed from the main electrical switchboard to replace the main lube oil pump attached to the PTO shaft.




Photo 4: Main lube oil attached pump

Upon approval of the calculations submitted by Scana Volda to Class (BV), the temporary repairs would be accepted by Class, provided a load test at the manufacturers premises would be concluded satisfactorily and the repairs endorsed by Scana Volda.

The primary cause of the sustained gear box damage seems to be the failure of the PTO shaft forward roller bearings.

The damages sustained by the propulsion and PTO gear wheels and the gear housing are consequential and were caused by the disintegrated roller bearing elements that fell down from the failed forward roller bearings and passed through the gear wheels below, causing also the grooving marks on the PTO shaft.

The most likely reason for the failure of the PTO shaft roller bearings is still under investigation, however at this stage the following possible causes are suspected:

"FS CHARLOTTE"

OCCURRENCE (cont.)

- A design failure resulting in insufficient lubrication of the failed roller bearings;
- A material breakdown of the roller bearings;
- A vibration problem of the gear box assembly with the PTO engaged;
- An alignment problem of the gear box assembly;

The low lubrication oil pressure from the attached lube oil pump with the PTO engaged appears to be the first indication before the roller bearing elements had become loose and therefore a thorough assessment of the pump condition seems to be relevant in order to ascertain the root cause of the sustained damage.

It should also be noted that the standby lube oil pump is normally expected to start automatically, when the lubrication oil pressure drops, which apparently did not occur.

For easier understanding, excerpts of the gearbox drawings and some more photographs are attached as per enclosures nos. 3 and 4 respectively.

Alcoitão, 10th July 2008

Drawn up without prejudice to liability on behalf of the Leading Hull Underwriters of M/V "FS CHARLOTTE"

for SOUTH EUROPE SCUA OFFICE LDA.

-1-1-1-9



YARDIMCI GEMI INSA A.S. Aydintepe Mahallesi Tersaneler Caddesi 50 Sokak No.7 81700 Tuzla Istanbul Republic of Turkey,

Attn: Husseyin Yardimci

Marseille, 10 July 2008

Dear Sir.

REF. FS CHARLOTTE EXHULL Nº040 **GUARANTEE UNDER ARTICLE IX**

We are contacting you formally in our capacity of Buyers from you of the vessel FS CHARLOTTE pursuant to an Acquisition Contract between us dated 17 December 2003.

As you are aware, the vessel suffered a failure of the propulsion system on 23 May this year 40nm West of Vigo, Spain. The vessel was subsequently towed to the Portuguese yard at Viana Do Castelo, where repairs are being undertaken. It is not expected that first temporary repairs will be completed until 10 August 2008 and final repairs to be completed by January / February 2009.

Investigations have revealed that the cause of the breakdown was a failure of the reduction gear PTO/PTI shaft bearings.

Since the Builder pursuant to Article IX of the Acquisition Contract guaranteed the propulsion system for a period of 36 months from delivery to Buyers, we now call upon you to comply with your contractual obligations to reimburse us for the cost of the repairs. You are of course invited to investigate the vessel where she is situated at present and to verify the facts for yourselves. We confirm that it is and has been impractical to bring the vessel to your premises in Turkey given the length of tow required and the vessel's service commitments.

In addition, please be aware that this sudden failure of the vessel's propulsion system raises several issues with regard to the vessel's future performance. We understand that the repairs presently being carried out may only be sufficient for a temporary basis, and that further, permanent, repairs to the vessel are likely to be required in January 2009, the earliest point at which, we are informed by Scana Volda that the full repair will be available.

The vessel is currently chartered on a long term charterparty under which Buyers have guaranteed the vessel's speed at 14 knots. We are informed that, in the period between temporary repairs and final permanent repairs, the vessel may not be able to achieve the speed of 14 knots, and that a speed of 10 to 11 knots would be more realistic. There may also be an adverse impact on the vessel's consumption of MDO resulting from this breakdown.

As well as suffering lost hire, Buyers may now also face claims from their charterers in respect of vessel underperformance, until such time as permanent repairs may be undertaken.

10, place de la Joheffe Les Docks, Atrium 10.7 B.P. 24606 13567 Marseille Cedex 02

161. 33 (0) 4 95 09 31 40 Eax: 33 (0) 4 95 09 31 49

s.k. an capital de 5 000 000 € - sirel 410 806 202 00025 - RCS Mareire B 410 806 202 - code NAC 6710

A Proforma guarantee/claims form is also attached in Appendix 2 hereto. We now call upon you to confirm that you accept responsibility for the defects and for the costs of repair.

Investigations by Buyers are ongoing and all of Buyers' rights under the Acquisition Contracts are fully reserved

Yours faithfully

Christian Garin

APPENDIX 1

	ESTIMATED PROVISIONAL REPAIRS	ESTIMATED FINAL REPAIRS
AGENCY & PORT	E SAN SE SELVANO - SE	60 000 €
TUG CONTRACT		50 000 €
SOB SCANA		25 000 €
ENVC		40 000 €
PEAR		60 000 €
MACHINING	75 000 €	<u> </u>
TEST AND LOAD	30 000 €	
TRANSPORT	9 000 €	
ENVC	30 000 €	
SOB SCANA	25 000 €	
NEW HOUSING		240 090 €
SPARE PARTS		163 000 €
NEW WHELLS		165 000 €
ENVC		30 000 €
TRANSPORT		5 000 €
SOB SCANA		40 000 €
PEAR		20 000 €
AGENCY & PORT		5 000 €
CLASS FEES	15 000 €	35 000 (
TOTAL TORIS	**************************************	

APPENDIX 2

CLAIMS FORM

GUARANTEE/CLAIMS FORM m/t "FS CHARLOTTE"

Document 1

1. Claim No. 18: head office claim

2.	Subject	Reduction gear breakdown
3,	Department	Technical department
4,	Date of observation	23 May 2008
5.	Date of informing the Company	29 May 2008
6.	Equipment	Main engine Reduction gear
7.	Manufacturer	SCANA VOLDA
8.	Drawing	VA204962
9.	Other indication	《新教育中中》

10. Description of defects, position etc. (as many details as possible):

Complete breakdown of the reduction gear.

Housing destroyed.

Vessel must be towed to nearest port

- 11. Necessary repairs (done by the crew). NA
- 12. Necessary repairs (to be carried out by shore repair company; shipyard etc):

Scana Volda Technicians have been requested to come on board as soon as possible to check the reduction gear

13. Spare Parts (required/to order etc.):

According to Scana Volda inspection

Reported by: A. Massot

Signature:

Date: 10 July 2008

223,303.02 € 18009445 101/16/2018 Padd 2 D 1.25007 (25,628.08 € 1800949) 101/2008 Padd 2 D 1.25008 (25,628.08 € 1800949) 111/2008 Padd 2 D 1.25008 (25,628.08 € 1800949) 111/2009 Padd 2 D 1.25009 Padd 2 D 1.25009 (25,628.08 € 1800949) 111/2009 Padd 2 D 1.25009 Padd 2 D	9,138 E 4,836 E	wsc wsc
223,303,02 € 18009413	6,338 E	D\$W
223,303.02 € 18000417 \$101/02/008 Paid 2 D 1.2007 \$25,028,08 € 180003917 \$11/02/2008 Paid 2 D 1.2007 \$31,916.93 € 18000497 311/02/2008 Paid 2 D 1.2007 \$44,16.0 € 18000497 31/10/2008 Paid 2 D 1.2001 \$31,916.93 € 18000497 31/10/2008 Paid 2 D 1.2001 \$32.0 € 18000497 31/10/2008 Paid 2 D 1.2001 \$32.0 € 18000497 31/10/2008 Paid 2 D 1.2001 \$32.0 € 18000497 31/10/2009 Paid 30 D 1.2001 \$31.0 € 290.3 L3 € CE60/2007 44/10/2009 Paid 40 D 1.2002 \$31.0 € 20000407 28/14/2009 Paid 50 D 1.2002 \$31.0 € 20000407 28/14/2009 Paid 50 D 1.2002 \$31.0 € 20000407 28/14/2009 Paid 50 D 1.2002 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000408 \$31.0 € 20000	:	Sch
223,303,02 € 18000414	5,952 €	Colum
223,303,02 € 38009414 1045/2008 Paid 2 D 1.5007 225,238,08 € 78009414 1125/2008 Paid 2 D 1.5007 313,916,39 € 78004639 7110/2008 Paid 2 D 1.5008 441,60 € 18809414 1125/2008 Paid 2 D 1.5008 1.04,523 € 18809439 411/2009 Paid 39 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 39 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 7 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 7 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 7 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 7 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 7 D 1.5042 \$16 1.04,523 € 18809439 411/2009 Paid 7 D 1.5043 \$16 1.04,523 € 18809410 411/2009 Paid 41 D 1.5046 \$16 1.04,523 € 18809410 411/2009 Paid 41 D 1.5049 \$16 1.04,523 € 18809410 41 D 1.5049 \$16 1.04,523 € 1880940 1170009 Paid 11 D \$18 \$10 1.04,523 € 1880940 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 14 D 1.5049 \$16 1.04,523 € 1880099 1170009 Paid 117009 \$10 1.04,523 € 1880099 1170009 Paid	3,534 C	DSW
223,303,02 € 18009414 1016/2008 Paid 1.0 25,628,08 € 18009414 112/52008 Paid 2.D 1.5009 313,916,39 € 18009434 112/52008 Paid 2.D 1.5708 \$439 441,50 € 18009434 112/52008 Paid 2.D 1.5708 \$439 1,045,23 € 18009434 417/009 Paid 39 D 1.5204 \$150 1,045,23 € 18009431 417/009 Paid 2.D 1.5204 \$150 1,045,24 € CE62780 27/52009 Paid 2.D 1.5204 \$150 1,045,24 € CE62780 27/52009 Paid 2.D 1.5204 \$150 1,547,24 € CE62780 27/52009 Paid 2.D 1.5204 \$150 2,936,13 € CE62780 27/52009 Paid 2.D 1.5204 \$150 2,936,13 € CE627817 41/2009 Paid 43 D 1.5208 \$150 165,247,34 € CE62797 42/4/2009 Paid 50 D 1.5208 \$150 165,247,34 € CE62797 42/4/2009 Paid 50 D 1.5208 \$150 165,247,34 € CE62797 42/4/2009 Paid 50 D 1.5208 \$150 165,247,34 € CE62797 42/4/2009 Paid 50 D 1.5208 \$150 165,247,34 € CE62797 42/4/2009 Paid 60 000 48 D 1.5208 \$150 165,324,00 € 20054045 37/2/2009 Paid 60 000 48 D 1.5208 \$150 165,324,00 € 20054045 37/2/2008 Paid 60 000 41 D 1.5208 \$150 166,318,00 € 20054045 37/2/2008 Paid 60 000 41 D 1.5208 \$150 121,177,16 € 23057347 57/2/2008 Paid 10 D 1.5208 \$150 21,177,16 € 23057347 57/2/2008 Paid 11 D 1.5209 \$150 21,177,16 € 23057347 57/2/2008 Paid 11 D 1.5209 \$150 21,177,16 € 23057347 57/2/2008 Paid 11 D 1.5209 \$150 21,177,16 € 23057347 57/2/2008 Paid 11 D 1.5209 \$150 21,177,16 € 23057347 57/17/2008 Paid 11 D 1.5209 \$150 21,177,16 € 23057347 57/17/2008 Paid 11 D 1.5209 \$150 21,177,16 € 23057347 57/17/2008 Paid 12 D 1.5209 \$150 21,177,17 € 8035097 11/17/2008 Paid 12 D 1.5209 \$150 21,171,17 € 8035097 11/17/2008 Paid 55 D 1.5209 \$150 21,171,17 € 8035097 11/17/2008 Paid 55 D 1.5209 \$25 25 5,150 26 5,250,16 € 7000209 700 11/17/2008 Paid 55 D 1.5209 \$25 25 5,150,16 € 7000209 700 11/17/2008 Paid 55 D 1.5209 \$25 25 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	9,997 €	Att
254,303,02 € 180004143 IVI6/2008 Paid 1.D 1.0007 533 25,628,08 € 180003911 811/2008 Paid 2.D 1.5708 313,916,92 € 180004391 410/2008 Paid 2.D 1.5708 449 1.5708 449 4.D 1.5708 449 4.D 1.5708 449 1.5708 449 4.D 1.5708 449 1.5709 4.D 1.5708 449 1.5718 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117 4117	\$4,188.43 3,083.81 €	Total
223,303,02 € 18000414 1016/2008 Paid 1.D 1.0007 533 25,628,08 € 18000491 \$11/2008 Paid 2.D 1.5708 \$313,916,93 € 180004991 \$11/2008 Paid 2.D 1.5708 \$439 13,916,93 € 18000444 11/25/2008 Paid 3.D 1.2811 \$1 1,045,23 € 180004851 417/2009 Paid 39.D 1.3942 \$1 1,141,43 € 262432204 417/2009 Paid 32.D 1.3947 \$10 15,472,48 € 26242827 417/2009 Paid 33.D 1.2891 \$16 2,306,13 € C56/2882 2720/2009 Paid 43.D 1.2782 \$1 4,247,24 € 2647C R0817 81/42/2009 Paid 43.D 1.2782 \$1 185,224,50 € 2647C R0817 81/42/2008 Paid for \$31,9 K€ 8.D 1.48907 \$1 293,300,40 € 2647C R0817 81/42/2008 Paid for \$31,9 K€ 8.D 1.48907 \$43 293,244,50 € 2668/278 31/42/2009 Paid for \$31,9 K€ 9.D 1.48907	50,000 6	Kotug
22,3,03,02 € 18000414	243.16 €	Brookes Bell
25,3,30,02 e 18009443 10/16/2008 Paid 1.0 25,528,08 e 18009443 10/16/2008 Paid 1.0 25,528,08 e 180094391 71/16/2008 Paid 1.0 25,528,08 e 180094391 71/16/2008 Paid 1.0 213,916,93 e 180094391 71/16/2008 Paid 2.0 21,045,23 e 180094391 41/12/3/2008 Paid 2.0 21,045,23 e 180094391 41/12/3/2009 Paid 2.0 21,04,00 e 180096485 41/12/3/2009648 41/12/2009648 41/12/2009648 41/12/2009648 41/12/2009648 41/12/2009648 41/12/2009648 41/12/2009648 41/12/2009648 41	B083039/2	Brookes Bell
25,3,30,02 € 18009474 \$ 10/16/2008 Paid 1.D 1.5012 \$ 133,916.93 € 18009391 \$ 8/11/2008 Paid 1.D 1.5012 \$ 133,916.93 € 18009459 7 11/02/2008 Paid 2.D 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012 \$ 1.5012	15,157.73 GBP 17,157.73 € 8083039/1	Brookes Bell
253,303,02 € 180004145 1016/2508 Paid 255,028,08 € 18000391 8/11/2008 Paid 255,028,08 € 18000391 8/11/2008 Paid 255,028,08 € 180004591 7110/25008 Paid 241,60 € 180004591 7110/25008 Paid 241,60 € 180004591 411725/2008 Paid 241,60 € 180004591 411725/2008 Paid 241,60 € 180004591 411725/2008 Paid 25,043,21 € 264/392104 417/2009 Paid 25,043,21 € 264/2826 417/2009 Paid 25,043,21 € 266/2810 417/2009 Paid 25,043,21 € 266/2810 417/2009 Paid 25,043,21 € 266/2810 417/2009 Paid 25,043,21 € 266/2817 417/2009 Paid 25,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,04 € 27,0	3,308.62 GBP 3,525.33 €	Neale consulting Engineers
253,303,02 € 180004145 1016/2008 Paid 25,528,08 € 180002911 8/11/2008 Paid 25,528,08 € 180002911 8/11/2008 Paid 213,916,93 € 180004591 7110/2008 Paid 214,60 € 180004591 7110/2008 Paid 22 D 1.2509 241,60 € 180004678 3/16/2009 Paid 22 D 1.2811 218,161,92 € 180004678 4/12/2009 Paid 22 D 1.2811 218,161,92 € 180004831 4/12/2009 Paid 21,845,41 € 2044332104 12/31/2009 Paid 25,50,471,48 € CE6/2826 2/20/2009 Paid 25,50,471,48 € CE6/2826 2/20/2009 Paid 25,50,471,48 € CE6/2827 4/5/2009 Paid 25,50,471,48 € CE6/2827 4/5/2009 Paid 25,50,43 € CE6/2827 4/5/2009 Paid 25,50,43 € CE6/2827 4/5/2009 Paid 25,50,43 € CE6/2827 4/24/2009 Paid 25,51,51,51,51,51,51,51,51,51,51,51,51,51	3,751.15 € @8/1780.P77@	Neale consulting Engineers
223,303,02 € 18000444\$ 10/16/20/08 Paid 2.25,228,08 € 18000459/1 \$1/120/08 Paid 2.2 D 1.5706 \$43 25,528,08 € 18000459/1 \$1/10/20/08 Paid 2.2 D 1.5706 \$43 441,00 € 18000459/1 \$1/10/20/08 Paid 2.2 D 1.2811 \$41,00 € 18000459/1 \$41/120/09 Paid 2.2 D 1.2811 \$41,00 € 18000459/1 \$41/120/09 Paid 2.2 D 1.2811 \$1,045.23 € 18000459/1 \$41/120/09 Paid 39 D 1.3246 \$45 128,161.92 € 18000459/1 \$41/120/09 Paid 39 D 1.3246 \$45 128,161.92 € 18000459/1 \$41/120/09 Paid 7.0 D 1.3907 \$1/10/16/16/16/16/16/16/16/16/16/16/16/16/16/	\$68,233.59 51,291.19 € 09-090	Bunker regularisation CSSA
223,303,02 € 180004145 10(16/2008 Paid 1.0	130,552.73 €	L.yandelibaseli
223,303,02 € 180004145 10(16/2008 Paid 1.0 1.5007 2.5,528,08 € 180004145 11(1/2008 Paid 1.0 1.5007 2.5,528,08 € 180004391 71(10/2008 Paid 1.0 1.5708 313,916,93 € 180004391 71(10/2008 Paid 1.0 1.5708 441 441,60 € 180004344 11/25/2008 Paid 2.2 D 1.2811 \$41,045,23 € 180004378 3/16/2009 Paid 39 D 1.2811 \$10,045,23 € 180004378 3/16/2009 Paid 39 D 1.2848 \$15,472,48 € C£6/2768 2/20/2009 Paid 7.0 1.3917 \$16,472,44 € C£6/2826 2/20/2009 Paid 7.0 1.3917 \$16,472,49 € ENVC R03117 4/24/2009 Paid 4.2 D 1.2782 \$16,5224.50 € ENVC R03117 8/14/2008 Paid 50 D 1.2782 \$16,5224.50 € ENVC R03117 8/14/2008 Paid 50 D 1.3232 \$1.2782 \$16,5224.50 € ENVC R03117 8/14/2008 Paid 50 D 1.3232 \$1.2782 \$16,5224.50 € ENVC R03117 8/14/2008 Paid 50 D 1.3232 \$1.2782 \$1.270,00 € 2005/6065 3/22/2009 Paid 50 0.0 48 D 1.3232 \$1.270,00 € 2005/6065 3/22/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € 900018 3/25/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 3/23/2009 Paid 50 0.0 48 D 1.3256 \$2.300,00 € PCO9007 \$2.300,00 €	\$12,864.74 10,086.60 €	Occan energy
223,303,02 € 180009448 100,02008 Paid 1.D 1.30007 25,538,08 € 180009391 101/2008 Paid 1.D 1.5700 531 23,39,16,93 € 180004391 7110/2008 Paid 4.D 1.5700 541 343,916,93 € 180004391 7110/2008 Paid 4.D 1.5700 541 1,045,23 € 180004391 4/1/25/2009 Paid 2.D 1.2811 541 1,045,23 € 180004891 4/1/2009 Paid 2.D 1.3042 541 17,453,41 € 2034332104 12/31/2009 Paid 7.D 1.3042 541 15,472,48 € CE6/2768 2/20/2009 Paid 7.D 1.3045 541 15,472,48 € CE6/2826 3/12/2009 Paid 7.D 1.3046 541 15,472,48 € CE6/2826 3/12/2009 Paid 7.D 1.3046 541 15,472,48 € CE6/2827 4/6/2009 Paid 50 D 1.3046 541 2,509,37 € CE6/2827 4/24/2009 Paid 50 D 1.3046 541 2,303,30,00 € 6/4/2 6/2009 Paid 50 D 1.3000 541 165,224,50 € 6/4/2 6/2009 Paid 50 D 1.3000 541 165,224,50 € 6/4/2 6/2009 Paid 50 D 1.3000 548 D 1.3000 540 550 D 1.3000 548 D 1.3000 550 S 1.30	\$34,751.74 21,707,60 €	GALP energia
223,303.02	\$35,558.24 23,752.90 €	GALP energia
223,930,02 € 188009448 1[0]60Z908 Paid 1.D 1.50007 25,528,08 € 1880094991 71[1/2008 Paid 2.D 1.5002 53] 25,528,08 € 1880094991 71[1/2008 Paid 4.D 1.5700 53] 441,60 € 188004949 11/25/2008 Paid 4.D 1.5700 54] 1,045,23 € 188004891 4/1/2009 Paid 39 D 1.2811 54] 1,045,23 € 188004891 4/1/2009 Paid 52 D 1.3246 54] 128,161,92 € 188004891 4/1/2009 Paid 52 D 1.3246 54] 128,161,92 € 188004891 12/31/2009 Paid 52 D 1.3246 54] 128,161,92 € 188004891 12/31/2009 Paid 52 D 1.3246 54] 128,161,92 € 188004891 12/31/2009 Paid 52 D 1.3246 54] 128,161,92 € 188004891 12/31/2009 Paid 52 D 1.3246 54] 128,161,92 € 188004891 12/31/2009 Paid 53 D 1.2782 54] 128,161,92 € 188004891 4/8/2009 Paid 53 D 1.2782 54] 128,161,92 € 188004891 4/8/2009 Paid 53 D 1.2782 54] 128,161,92 € 188004891 4/8/2009 Paid 67 531,9 K€ 8 D 1.3496 54] 129,320,00 € 188004917 8/14/2008 Paid 67 531,9 K€ 9 D 1.3496 54] 129,320,00 € 188004917 8/14/2009 Paid 67 531,9 K€ 9 D 1.3496 54] 128,107,00 € 188004917 8/14/2009 Paid 67 531,9 K€ 9 D 1.3496 54] 128,107,00 € 188004917 8/14/2009 Paid 67 531,9 K€ 9 D 1.3496 54] 128,107,00 € 18800491 5/28/2009 Paid 68 500 48 D 1.3497 54] 128,107,00 € 18800491 5/28/2009 Paid 68 500 48 D 1.3496 54] 128,107,00 € 18800491 5/28/2009 Paid 68 500 48 D 1.3496 54] 128,107,00 € 18800491 5/28/2009 Paid 68 500 54 54 54 54 54 54 54 54 54 54 54 54 54	\$33,407.31 22,670.20 €	GALP energia
223,303.02 € 188009448 1046/25018 Paid 1.D 1.55007 25,528,08 € 188009499 1 11/250208 Paid 2.D 1.55002 \$31 25,528,08 € 188009499 1 7110/2008 Paid 4.D 1.57008 \$31 24,16.03 € 188009494 11/25/2008 Paid 2.D 1.57008 \$45 1,045,23 € 1880094851 4/1/2009 Paid 39 D 1.2811 \$41 1,045,23 € 1880094851 4/1/2009 Paid 52 D 1.3246 \$31 174,453,41 € 2634332104 12/31/2009 Paid 52 D 1.3246 \$31 175,472,48 € CE6/2826 3/12/2009 Paid 33 D 1.28917 \$11 175,470,48 € CE6/2826 3/12/2009 Paid 42 D 1.2762 \$31 175,472,48 € CE6/2826 3/12/2009 Paid 42 D 1.2762 \$31 185,272,45,0 € ENFC R03117 8/14/2009 Paid 50 D 1.3246 \$31 185,272,45,0 € ENFC R03117 8/14/2008 Paid for \$31,9 K€ 8 D 1.3246 \$31 185,272,45,0 € ENFC R03117 8/14/2008 Paid for \$31,9 K€ 9 D 1.3249 \$31 185,272,45,0 € ENFC R03117 8/14/2008 Paid for \$31,9 K€ 9 D 1.3249 \$31 185,272,45,0 € 9201/42 3/18/2009 Paid / 30 000 48 D 1.3697 \$41 185,35,00 € 20056065 3/24/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 20056065 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 20056065 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 20056065 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.3697 \$31 185,35,00 € 900018 3/23/2009 Paid / 30 000 48 D 1.36	\$30,722.71 21,177.16 €	GALP energia
223,303,02 € 188009448 1046/25018 Paid 1.D 25,528,08 € 188009311 \$101/25028 Paid 1.D 25,528,08 € 188004391 \$110/2508 Paid 2.D 313,916,93 € 188004391 \$110/2508 Paid 4.D 313,916,93 € 188004391 \$110/2508 Paid 4.D 441,60 € 188004391 \$110/2508 Paid 2.D 1,045,23 € 188004391 \$471/2009 Paid 52.D 1,045,23 € 188004391 \$471/2009 Paid 52.D 1,045,23 € 188004391 \$471/2009 Paid 52.D 1,045,34 € 264/2826 \$120/2009 Paid 52.D 1,3248 € 266/2828 \$122/2009 Paid 52.D 2,340,34 € 266/2828 \$122/2009 Paid 53.D 1,259,37 € 266/2810 \$112/2009 Paid 42.D 2,343,13 € 266/2897 \$424/2009 Paid 50.D 1,2782 \$1.2782 293,30,40 € 644/2708 Paid 66 000 \$1.3248 \$1.2782 293,30,40 € 644/2708 Paid 70.000 \$48.D 1,335,40 € 2005/065 \$128/2009 Paid 70.000 \$48.D 1,34907 \$4.35,40 € 2006/66 \$128/2009 Paid 70.000 \$48.D 1,34907 \$4.35,40 € 2006/66 \$128/2009 Paid 70.000 \$48.D 1,34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1.34908 \$1	\$39,956.68 27,1 18.69 €	Bunker costs
223,303,02 € 188009448 1[0]60Z9018 Paid 1.D 1.25020	2,340,90 €	Contrôles alignements au taser
223,303,02 € 180009448 10/16/2008 Paid 1.D 1.35007 25,528,08 € 180009591 11/1/2008 Paid 2 D 1.5708 \$45 313,916,93 € 180004591 71/10/2008 Paid 4 D 1.5708 \$45 1,045,23 € 180004578 11/25/2008 Paid 22 D 1.2811 1,045,23 € 180004678 11/25/2008 Paid 39 D 1.2811 1,045,23 € 180004678 11/25/2009 Paid 39 D 1.3042 \$16 128,161,92 € 180004678 1/17/2009 Paid 39 D 1.3046 \$16 171,453,41 € 2634332164 12/31/2009 Paid 7 D 1.3246 \$16 15,472,48 € CE6/2826 2/20/2009 Paid 7 D 1.3947 \$16 15,472,48 € CE6/2826 2/20/2009 Paid 42 D 1.2811 \$1 15,472,48 € CE6/2826 2/20/2009 Paid 42 D 1.2782 \$16 2,509,37 € CE6/2849 44/2009 Paid 43 D 1.2782 \$16 2,509,37 € CE6/2849 44/2009 Paid 50 D 1.3496 \$1 1,273,38 € CE6/2907 42/2009 Paid 50 D 1.3496 \$1 1,273,38 € CE6/2907 42/2009 Paid 51 D 1.3232 \$1 165,224,50 € ENFC R08117 8/14/2008 Paid for \$31,9 K€ \$1 D 1.3232 \$1 165,224,50 € ENFC R08117 8/14/2008 Paid 60 \$19 K€ \$1 D 1.3656 \$1 2,307,00 € 200250065 3/24/2009 Paid 60 00 41 D 1.3656 \$8 2,307,00 € 200250065 3/24/2009 Paid 60 00 41 D 1.3656 \$8	16,135.00 €	Intervention octobre 2008- Janvier 2009
223,303,02 € 180004445 10/16/2008 Paid 1.D 1.55007 25,528,08 € 180004391 11/15/2008 Paid 2 D 1.5708 \$45 313,916,93 € 180004391 11/15/2008 Paid 4 D 1.5708 \$45 1,045,23 € 180004391 41/125/2008 Paid 22 D 1.2811 1.045,23 € 180004678 41/15/2009 Paid 39 D 1.3042 \$45 1,045,23 € 180004678 41/15/2009 Paid 39 D 1.3046 \$45 128,161,92 € 180004679 41/15/2009 Paid 7 D 1.3246 \$16 171,453,41 € 2034332104 12/31/2009 Paid 7 D 1.3947 \$11 15,472,48 € CE6/2826 22/07/2009 Paid 7 D 1.3947 \$11 15,472,48 € CE6/2826 22/07/2009 Paid 33 D 1.2581 \$11 15,472,48 € CE6/2826 22/07/2009 Paid 42 D 1.2782 \$16,327,38 € CE6/2826 24/52009 Paid 50 D 1.3496 \$16 2,509,37 € CE6/2842 44/52009 Paid 50 D 1.3496 \$16 1,237,38 € CE6/2907 42/4/2009 Paid 50 D 1.3496 \$16 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid for \$31,9 K€ 8 D 1.3232 \$11 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid for \$31,9 K€ 8 D 1.3232 \$11 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$13,9 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$13,9 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$1,3 K€ 9 D 1.3256 \$10 2,93,320,00 € 6/VFC R08117 8/14/2008 Paid 60 \$10 2,93,320,00 € 6/VFC R08117 8/14/20		Essais en mer à Murseille
223,903,02 € 188009448 1046/2008 Paid 1.D 1.55007 25,538,08 € 188009449 11/25008 Paid 2.D 1.5708 313,916,93 € 1880094391 71/10/2008 Paid 4.D 1.5708 \$45 441,60 € 188009439 11/25/2008 Paid 2.D 1.2811 441,60 € 188009439 11/25/2008 Paid 39 D 1.2811 1,045,23 € 188009439 4/17/2009 Paid 39 D 1.3042 \$45 128,161,92 € 1880094891 4/17/2009 Paid 7.D 1.3246 \$16 177,453,41 € 2034932104 12/31/2008 paid 7.D 1.3947 \$11 15,472,48 € CE6/2768 2/20/2009 paid 7.D 1.3947 \$11 15,472,48 € CE6/2826 2/20/2009 paid 33 D 1.2891 \$1 2,593,7 € CE6/2826 3/12/2009 paid 42 D 1.2782 \$12 2,936,13 € CE6/2826 4/6/2009 paid 50 D 1.3496 \$1 2,376,13 € CE6/2827 4/24/2009 paid 50 D 1.3496 \$1 165,224,50 € ENFC R08117 8/14/2008 paid for \$31,9 K€ 8 D 1.3232 \$1 165,224,50 € ENFC R08117 8/14/2008 paid for \$31,9 K€ 8 D 1.3232 \$1 293,330,00 € 6/4FC R08117 8/14/2008 paid for \$31,9 K€ 8 D 1.3232 \$1 4,000,00 € 920142 3/18/2009 Paid /30 000 48 D 1.333 \$5		·
223,903,02 € 188009448 10(16/25018 Paid 1.D 1.55007 1.25(1.5)(2.5)(2.5)(2.5)(2.5)(2.5)(2.5)(2.5)(2	96,000.00 €	Assistance remontage du réducteur Scana Volda
223,903,02 € 188009448 1[0]60Z9018 Paid 1.D 1.55007 25,628,08 € 188009491 1251/2008 Paid 2.D 1.5502 53 313,916,93 € 188004591 7110/2008 Paid 4.D 1.5708 54 313,916,93 € 188004591 7110/2008 Paid 4.D 1.5708 54 441,60 € 188004494 1125/2008 Paid 22 D 1.2811 54 1,045,23 € 188004851 4/172009 Paid 39 D 1.3042 51 17,453,41 € 2034332/04 12/31/2009 Paid 72 D 1.3246 51 15,472,48 € CE6/2768 2/20/2009 Paid 73 D 1.3917 51 173,09,37 € CE6/2826 3/12/2009 Paid 33 D 1.2782 51 2,593,37 € CE6/2826 3/12/2009 Paid 43 D 1.2782 51 2,593,37 € CE6/2827 4/24/2009 Paid 50 D 1.3496 50 D 1.3496 50 D 1.3496 50 D 1.3496 50 D 1.3232 51 185,224,50 € ENFC R08117 8/14/2008 Paid for \$31,9 K€ 8 D 1.3232 51	293,320,⊕0 € ENFC ROS117	Gear box works
223,903,02 € 180009448 10(46/2008 Paid 1.D 1.50720 Six 25,628,08 € 180009491 811/2008 Paid 1.D 1.50720 Six 25,628,08 € 180004991 71(10/2008 Paid 2.D 1.50720 Six 213,916,93 € 180004991 71(10/2008 Paid 4.D 1.5708 Six 213,916,93 € 180004991 11/25/2008 Paid 2.D 1.2811 Six 11,045,23 € 180004078 41/25/2009 Paid 39 D 1.3042 Six 215,472,48 € C26/2788 12/31/2009 Paid 52 D 1.3046 Six 215,472,48 € C26/2788 12/31/2009 Paid 33 D 1.2591 Six 23,00 € C26/2891 12/2009 Paid 4.5 D 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.2782 1.27	105,224.50 € ENFC ROSH7	General services
223,303.02	CE6/2907	SEA invest
223,303,02 € 18000448	CE6/2883	SEA invest
223,303,02 € 18000443	CE6/2810	SEA invest
223,303,02 € 18000448 1076/25018 Paid 1.D 1.55007 25,528,08 € 180004391 \$11/25008 Paid 2.D 1.5708 213,916,93 € 180004391 7110/2008 Paid 4.D 1.5708 \$44 213,916,93 € 180004391 7110/2008 Paid 2.D 1.2841 441,60 € 180004374 11/25/2508 Paid 2.D 1.2841 1,045,23 € 180004678 3/16/2009 Paid 39 D 1.3042 \$16 128,161,92 € 180004678 417/2009 Paid 52 D 1.3246 \$16 174,433,41 € 2034332144 12/31/25008 paid 7 D 1.3947 \$16 15,472,48 € CE6/2768 2/20/2509 paid 33 D 1.2581 \$1	CE6/2826	SEA invest
223,903,02.6 180009145 10165/28018 Paid 1.D 1.50007 25,528,08 € 18000911 8911/29008 Paid 2.D 1.5012 25,528,08 € 180004591 7110/2008 Paid 4.D 1.5708 313,916,93 € 180004591 7110/2008 Paid 4.D 1.5708 441,60 € 180004474 11/25/2008 Paid 22.D 1.2811 1,045,23 € 180004678 3/16/2009 Paid 39.D 1.3042 128,161,92 € 180004851 4/17/2009 Paid 52.D 1.3246 77,453,41 € 2034332104 12/331/2008 paid 7.D 1.3947	15,472.48 € CE61768	SEA invest
223,303,026 180009145 10160/2008 Paid 1.D 1.50007 25,628,08 6 180009191 8911/2008 Paid 2.D 1.5012 25,628,03 6 180004591 7110/2008 Paid 4.D 1.5708 313,916,93 6 180004591 7110/2008 Paid 4.D 1.5708 441,60 6 180004144 11/25/2008 Paid 22.D 1.2511 1,045,23 6 180004678 3/16/2009 Paid 39.D 1.3042 128,161,92 6 180004851 4/17/2009 Paid 52.D 1.3246	77,453,41 € 2034332104 1	Barwill/ Port expenses Viana do Castelo
223,303,026 180009145 10 165/28018 Paid 1.D 1.50007 225,628,086 1800003911 8711/2008 Paid 2.D 1.5012 313,916,936 180004591 7110/2008 Paid 4.D 1.5708 441,606 180004144 11/25/28008 Paid 22.D 1.2811 1,045,236 180004678 3/16/2809 Paid 39.D 1.3042	1,133,173.50 128,161.92 6	
223,303.02 € 180004145 10/16/23008 Paid 1.D 1.50007 25,628,08 € 180003911 8/11/23008 Paid 2.D 1.5002 313,916,93 € 180004591 7/10/2008 Paid 4.D 1.5708 441,60 € 180004144 11/25/2308 Paid 22.D 1.2811	9,332,38 1,045,23 € 180004678	Pressure block
223,303.02 € 180004145 10/16/23008 Paid 1.D 1.50007 25,628,08 € 180003911 8/11/23008 Paid 2 D 1.5002 313,916,93 € 180004591 7/10/2008 Paid 4 D 1.5708	4,000.00 441.60 € 186004144	Freight of defect parts
223,303.02 € 180009148 10/16/2308 Paid 1.D 1.5012 25,628,08 € 180003911 8/11/2308 Paid 2 D 1.5012	2,505,322.67 313,916.93 € 180004591	Main Gear Wheels and spare parts
223,303,02 @ 180004145 10/16/2008 Paid LD 155551	25,628,08 € 180003911	gos
	1,868,644,56 223,303,02 € 18000414S	8
117,290,00 € 180004145 6/5/2008 Paid 1 D 1.5402	925,000,00 117,290,00 € 180004143	New sear box housing
	Invoice No	Definitive renairs & casts

\$304,502,70					a coope		Ü
\$3,039.84	1.2967	31 P	2/10/2009 paid	8165497	2.807 6		Att.
838,219,76	1.3262	21 F	1/13/2009 paid	8162469	28,819 €		A8
\$61,933.95	1.3731	18 P	10/8/2008 paid		45,105.20 €		Lariosa tugs shipping
\$56,374,00	1,4081	17 P	10/1/2008 paid	17/01/296908	3 (40,040		onimine sent assume 1
\$1,449,01	1.2984	37 P	1/22/2009 paid	T308603	1,116.80 €		Works carried out in Vista do Castello
\$7,687,49	1.2967	36 P	2/10/2009 paid	TH09901	5,928.50 €		Weeks carried out in Vinna do Castello
S17,424,11	1.3042	28 P	3/16/2009 Paid	827670	(3,360.00 €		A existance denoise d'un réducteur Scans Volda
39,809,94	1.2623	24 P	12/3/2008 paid	E 451124198147/o/sfs	7,771.48 €		KAMAR / nort expenses Crahes
44 to 200 04	3.4Q00	67	9/12/2008 Paid	180004016	8,909.31 €	71,217.50	Stand By burns & Starter
60 0 53 0 X2	1.3700	ינו דיית	7/16/2008 Paid	180004599	10,290.80 €	81,411.00	SOB
\$16.073.41	1.635.1	; t.	11/25/2008 Paid	180004163	62,024.32 €	561,814.50	SOB
\$79,459,36	1 2811	7 1					Provisional repairs of costs



NOTICE OF DEFECTS & REPAIRS

URGENT

YARDIMCI GEMI INSA A.S. Aydintepe Mahallesi Tersaneler Caddesi 50 Sokak No.7 81700 Tuzla Istanbul Republic of Turkey,

Attn: Huseyin Yardimci

Marseille, 17 June 2006

Dear Sirs,

REF. FS CHARLOTTE EXHULL Nº040 GUARANTEE UNDER ARTICLE IX

We hereby refer to the acquisition contract dated 17 December 2003 (the "Acquisition Contract") entered into between FOUQUET SACOP SA as buyer (the "Buyer") and YARDIMCI GEMI INSA A.S. as builder (the "Builder") regarding the construction of a molten sulphur & asphalt tanker identified under Hull No 040 at time of construction and presently called as FS CHARLOTTE.

In compliance with provision of Article IX (Warranty of Quality) of the Acquisition Contract and further to:

- (i) our notice of defects dated 30th May 2006 with enclosures,
- (ii) our meeting dated 6th June 2006 in BAYONNE (FRANCE) with your guarantee engineer, Mr. GOKHAN KOGAR and
- (iii) the meeting held on 11th and 12th June in JORF LASFAR (MOROCCO) with your guarantee engineers, Mr. GOKHAN KOGAR and Mr. OSMAN YALMAN,

we hereby notify you that vessel FS CHARLOTTE will be in ST NAZAIRE Friday night 16th June 2006 (ETA) for repairs as discussed with your engineers and subcontractors.

10, place de la Johette Les Docks, African 10.7 8 P. 24606 13567 Marselle Cedex 02

2

You will find hereafter the details of the contemplated repairs as per quotation.

We ask you to attend theses repairs or confirm your comments on the way they will be carried out due to the fact that these defects fall within the scope of the guarantee of the Builder as per the Acquisition Contract.

The defects to date and proposed repairs are listed in Appendix 1 hereto together with the list of items/costs already borne by our company attached in Appendix 2 hereto

We would be very grateful if you could confirm your acceptance that all these items listed in Appendixes 1 and 2 hereto are covered under Article IX of the Construction Contract and therefore that the Builder will bear these costs by returning to my attention (fflevet@fsm.fr) a duly signed copy of this letter.

Yours faithfully,

Frédéric Fievet

Confirmed and agreed for and on behalf of Yardimci Gemi Insa A.S.

Huseyin Yardimci

APPENDIX 1

LIST OF DEFECTS: REPAIRS WITH CORRESPONDING COSTS

TO BE DONE

FLAG / OCIMF/VARIOUS CONDITIONS			Following 96/04 & 12/96 survey on board Cloughts of fines & valves	Yardimc) / हेट
30 036 €	work	quotation	Subcontrator	Comments
CCIMP Moning guideline complemen	_! Landmarks on winch (60% SWL) & win8ass	1 500 6	C Daird Hussairo Maritro	supply only. Fixing by slip's tiet
Field condition to be studed 38/36/3006	Fwd waterlight door to be received	200 €	E Saint Nazelre Meisna	
Fing conditionallyC to be closed 38/06/2005	Cargo tank vestilation shall be useable (Z4) a day) at sea whitever condition; versiosed by five mast	6 545 6	E Baict Mazoka Madine	
Fing conditionSEC is be sleet 3005(7008	Void Space vent head filters	2 100 6	Sakit Nazake Martina	cupply of 4 filters to be fished by elaptic starti
Phage condition to be aboved \$8006/2006	Five emergency ladder device	200 (Soun Nouselve Marino	
Plag condition to be alocad 30/08/2008	gas detection; remote audibit/visible alarm on bridge & pumproom	17 390 (Shipelec	Including Calde passage from CCR to make seck and to bridge
Fing condition to be desert 30/08/2006	upgrading of Pump roum sything/ien control (local switch on/off)			
Filing condition to be closed 30/06/2006	Upgrading of lighting of Pumproom			
FV contact nation tradeon	Port Aft Fan noisy and air flow restricted by upper deck	300 (E Saind Massellin Shading	
Vold Space ordinare Britisha	remote control of void space high level aform	300 €	Supply only (extremion)	foliog by stilling anythe state
Forecastle teleps wystem	Add Air driven hilge pump forward	1 500 €	Supply only (east-ration)	feeling by phylic strip's stell
Yank (क्था) सुन्यास्था।	SAAB 508 requested for adjustments		SAAB	Superior ESR via Yardiatic
Propeksus plant regulation	MAK / SCARA SOS requested for adjustments		Meax / Scana	Guarantee SOB via Yerdimoi
AUE gener bose driven pump helium	SCANA SOB requested for pump overhauling 6 gear box crecking		SCAHA	Guarantee SOR vis Yardynd

Cargo Pumps plant as per specification	800 obmiri disharging rate - Ruming in paratlel - packing seals oil leakage -		Following Saltifold Bayonne on board Menting	Yardinack / FB / FG / BURG NA
72 328 €	work	quotation	Subcontrator	Continuents
	Non return Velve on head of pumps / supply	€ 203 €	25-kt	
	Non return Valve on head of pumps / fitting	4 430 €	Şalın Mermire Merine	
	Cisplacement Discharge valves of Curgo pumps	8 613 €	Spains Massaline Allephino	
	Cismenting / Reliting of 4 latet steel expansion joints	980 €	Sairs Name in Markey	
	Alteration / adjustment septing of the	300 €	Bales Nazaira Marina	
	packing seel Spare parts	43 600 €	Birihuma ~	renewal of 4 packing on each authors porto
	Overhauting of Cargo pump packing Sest	6 000 €	Gurginani SOS	3 days of 7504 per days
	Overhausing of Cargo pump packing Sast		Baneren / PS 508	Quarentes 506 via Yeading
	Safety monitoring system on DP packing Seal / Infet chamber		PG SOB	Gueranian GOS via Yamined

Thermat Oil Tracing system as per specification	Vessel to load/carry/discharge Asphalt at 250° & Molten Sulphur at 150°	Fe	allowing DPDs \$ 1206 envey on bourd. Clogging of lines & vulves	Yestflanci i F5 / 3 WAN
215 020 €	work	quotation	Subcontrator	Convients
inadequate or missing thering exchen on spitce & popher lines	Asphalt / Moltan Sulphur Thermal Oit cargo lines Tracing specialist to be used	156 640 €	THERUSEX	Encluding supply / Engineering. 808.
cifus & Asorius than tracing salasyral	Thermex tracing system litting based on 2 X 80 ML on deck & on 2 X 40 ML in pump rooms as per Thermex	16 380 €	Salid Mazainy Maring (petingulory)	Suped on 68,2567-4.
Secondary thermal CC Symmol guillatient for eights Sour & valves external trading	Primary thermal oil system to be permanently connected and secured (valin two valves) to external tracing	6 000 €	Şaipt Mazajra Masino (rationatica)	
datesisch man uft	Primary thermat oil on sulfur lines monkoving	€ 0000 €	SPSPELEC (WYSTREWS)	PT 100 samples on Thermal &
Seeing Tracing of CT Intel Bons in	Add THERMON system on 11 Inlet lines (Veid Spaces)	30 000 €	THERMORY (cethrolibus)	statis including SOS / \$2 kg by \$2 kg

insulation of cargo lines, valves as per standards	Vessel to load/carry/discharge Asphalt at 250° & Molten Sulphur at 150°		Pollowing 8496 & 12196 servey on Speed. Cloughly of Spee & values	Hot semmethy insulators cyncies sharp reported the special descrip- ted sizes and the special description of the special speci
68 252 €	work	nolisioup	Subcontrator	Comments
New lossification of caupo lines	.r 248 ML of cargo pipes insulation (deck and pump room)	48 968 €	E ARI	including technical file
	10 cargo valves on dack insulation	3 021 €	. ARI	
	15 ML tank variatine cracked insulation to be renewed (Frost of FWO pump room)	2 962 €	AFI	
	23 Valves Insulation in pump Room	4 806 €	E NA	
	4+2 filters insulation (pump moin)	2 000 €	API (estimation)	
	11 Mt. cergo špes insulation in Void Špaces	3 300 €	AFE (estimation)	
	Stagging in pump Rooms	5 000 e	(actimities) IPA	

arious Costs	TECHNICAL CALL COSTS			
25 000 €	wark	quotation	Subcontrator	Constants
	SV / Flag Survey	\$ 000 €		Ecomejiu)
	15 D Technical call costs	20 000 €	Benty chiralcal (1979 / ट्राम्म) अपने (Tag	(Colon) nibint
	PRG	/TOTAL 411 833 €		
	ALREADY E	IGAGED 8 157 6	ર્દ્ધ અફેશ્વરોન્ક્લે ઉદિ	
		419 790 €		

5

APPENDIX 2

LIST OF DEFECTS/REPAIRS

ALREADY INCURRED BY THE BUYER

Unforeseen - Technical

DES/RMS	Code FSM	OFS/RMS فالم	Fournissaur	Montant Commande	Cerreports
CHA/RM-31/1	273	16/03/06	SAAÐ ROSEMOUNT	€ .	Gas detection commissionning (class condition) : charge, if any to be suspended by Yarokino
CHA/RM-35/1	272	17/03/08	SIEMENS	€ -	Fire detection commissionality charge, if any to be supported by Yardanci
CHARM-201	129	22/03/06	THERMON	€ 1803,12	comments remarcantally of Sulfur Bress)
CHA/RM-45/1	710	07/04/08	GONZALEZ & FILS	€ 420,20	Power Pack Failure
CHA/RM-50/1	111	10/64/06	PG Marine Groupe ing Per Gjentrum A5	ŧ .	Cargo punty falkue charge, if any to be suppointed by Yandinyo
CHA/RM-55/1	111	18/04/08	PG Marine Groupe Ing Per Gjerdrum AS	€	Cargo punto falcare charge, if biry in he supported by Yankinti
CHA/RM-57 / 1	111	18/04/06	PG Marine Groupe ing Per Gjerdrum AS	€ .	Cargo punts feature sharps, if say to be supported by Yanding
CHA/RM-61/1	210	25/04/06	SAREM	€ 2,790,00	Archus fullumes i primitiny heating on bulliot corgo- lignas.
CHAVSIE/FE-33 / 1	530	05/04/06	SPRI	€ 1.454,80	Various valves to connect primary thermal Oil on suffer period plant meating soils.
FREE INVOICE	110	30/04/08	ETNA	€ 1,689,00	ಧೀನ್ವಾದ ಅಭಿವರ್ಧಗಾಣಕ ರಾಜನಾಗಕಾನಂಭಾಗಿಸುತ್ತಬೇಕೆಂದು

ALREADY ENGAGED € 8 157,12



NOTICE OF DEFECTS & REPAIRS

URGENT

YARDIMCI GEMI INSA A.S. Aydintepe Mahallesi Tersaneler Caddesi 50 Sokak No. 7 81700 Tuzla Istanbul Republic of Turkey,

Attn: Husseyin Yardimci

Marseille, 9 October 2006

Dear Sirs.

REF. FS CHARLOTTE EXHULL Nº040 GUARANTEE UNDER ARTICLE IX

We hereby refer to the acquisition contract dated 17 December 2003 (the "Acquisition Contract") entered into between FOUQUET SACOP SA as buyer (the "Buyer") and YARDIMCI GEMI INSA A.S. as builder (the "Builder") regarding the construction of a molten sulphur & asphalt tanker identified under Hull No 040 at time of construction and presently called as FS CHARLOTTE.

We also hereby refer to:

- · 85 guarantee claims already sent to your Office.
- Various exchanges with your Guarantee Engineer during signing on period (from 09/03/06 to 02/04/06). At this date, it was agreed to sign him off due to due to lack of cabins on board after Reinforcement of ship's staff by a necessary Painting & cleaning gang
- 30/05/2006 Statement of facts sent to Your Office.
- 06/06/2006 FS / YARDIMCI / PG / S MAN on Board meeting at Bayonne.
- 10/06 to 13/06 FS / YARDIMCI / S MAN on Board Survey at JORF LASFAR.
- 17/06/06 Notice of defects sent to your Office.
- 19/06/06 On Board meeting with FS / YARDIMCI / NAVYTECH at SAINT NAZAIRE as introduction of technical call.
- 26/06/2006 On Board Meeting FS / YARDIMCI for review of final list of works carried out at ST NAZAIRE.
- 14/07/2006 On board meeting FS / BORNMANN at JORF LASFAR.

 11/08/2006 BORNEMANN Office Meeting FS / YARDIMCI / PG / BORNEMANN at OBERNKIRCHEN (GERMANY)

We hereby notify you that vessel FS CHARLOTTE is in ST NAZAIRE as from today's date for a tenday period for repairs as discussed with your engineers and subcontractors.

You will find hereafter the details of the contemplated repairs as per quotation.

We ask you to attend theses repairs or confirm your comments on the way they will be carried out due to the fact that these defects fall within the scope of the guarantee of the Builder as per the Acquisition Contract.

The defects to date and proposed repairs are listed in Appendix 1 hereto.

We would be very grateful if you could confirm your acceptance that all these items listed in Appendix I hereto are covered under Article IX of the Construction Contract and therefore that the Builder will bear these costs by returning to my attention (ffievet@fsm.fr) a duly signed copy of this letter.

Yours faithfully,

Confirmed and agreed for and on behalf of Yardimci Gemi Insa A.S.

Frédéric Fievet

Husseyin Yardimci

APPENDIX 1

LIST OF DEFECTS AND REPAIRS WITH CORRESPONDING COSTS TO BE DONE IN TECHNICAL CALL SCHEDULED IN OCTOBER

62 382 €	FLAG / OCIMFIVARIOUS conditions	quotation	Subcontrator	Comments
SI NAZAIRE OCT 06	Leadmarks on winch (60% SWL) & windless	2 300 €	Seint Nazaire Merine	
•	Fwd wefertight doors to be renewed	1 590 6	Salat Nazaire Marine	
	nish engine driven lub oli pump oli pipe lo change	2 370 €	Saint Nazaire Marine	
	Bow Thruster sale acces	1 500 €	Saint Nazaire Matino	
	Crip tray pipes	712€	Saint Nazaire Marine	
	New "Bas JAFRET" (1 intito protect the crune)	9 000 €	Saint Nazaire Marine	
	port and storboard winless lignment / CL 814	30 000 €	Saint Nazaire Marine	
	COSTS OF TECHNICAL CALL (Pitot, Berth, ISPS, Chemical, Marpol)	15 000 €	SEA INVEST	
266 912 €	Cargo Pumps plant as per specification	quotation	Subcontrator	Comments
SENAZAIRE OCT 06	upgrading sealing system according to bomemann recomm	34 018 €	Per Gjerdrum AS	
	4 etc motors 0,65hw for searing pump & 1 (an expling for PC Console	3 350 €	Per Gjerdrum AS	
	1 slec motor 17 kw for secundary thermal Oil pump	1755€	Per Gjerdrom AS	
	Sealing Piping on sulfur pump & Bitumen pumps as per PG/ Bernamann recommendations (including air on tanks)	17 848 €	Saint Nazatra Marine	
	Sealing Piping on Emergency sulfur pump as per PEJ Bornemann recommendations (including air on tanks)	6 804 €	Saint Nazaire Marino	
	tectating valves on sealing heater	1900€	Saird Nazaire Marine	
	flushing of hydraulic lines and new sealing lines as per PG and Bornemann request	6 000 €	Saint Nazaire Marine	
	"KCOIV". Oil to be ased for Woyleu arithma cardo twinib	14 000 €	7€ basad 2000)	
	Overhauling of Cargo pump packing seals	4 500 €	Board Service engineer on	
	packing seal Spare parts	16.000 €	Burgmann	
	Check of Cargo pump bearing cooling cooling		Per Gjerdrum AS	
	service on board for upgrading sealing system on machanical seals and sensors on cargo lines	15 000 6	bomensn, PG муд burgman	
	fitting new cables, starters, for new electric motors, sensors	41 764 6	SHIPELEC	
*	parts for new staters and electric motors in place of hydraulic motor. Permanent problems with hydraulic control and speed on hydraulic motors	d 45 338 f	SHIPELEC	CHA/SIE/FE/186
	Fitting of etc motor on analing pump (S MAN Pump (including builthead)	7 500	El Saint Nazoire Marine	
	2 Bitumen Emergency Рипра	25 600	€ BLACKMER	CHA/SIE/FE-98
	Filling of 2 Emergency tillumen Pump	1 850	E Saint Nazaire Marine	
	suction and deliverypipes & valves modification to; new bitumen cargo pumps	10 575	6 Saint Nazaire Matine	
	2 emergency flexible cargo hose, suction and delivery for emergency bitumen pumps	6 000	€ BfCCK£FEX	

161 536 €	Thermal Oil Tracing system as per specification	quotation	Subcontrator	Curaments
SI NAZAIRE OCT 06	3 way valves to connect definitively primary thermal Oil on sulfur cargo pipes heating coils.	7 306 6	SPRI	CHA/SIE/FE-88
	shuldown valve between primary and secondary tracing system	673 G	SPRI	CHASIE/FE-91
	control of shutdown valve between primary and accordary tracing system	141 €	SPRI	CHANJEATE-93
	fitting new HT 3 way valves on tracing system (including Shut Dawn)	3 736 €	Saint Nazake Morine	
	Tracing system bitumen pipes in pump room and omergoncy suiphur pipes	100 009 €	THERMEX	CHA/SIE/FE-83
	Tracing system bitumen pipes in pump soom and emergency sulphur pipes	12 041 €	THERMEX	CHAVSTE/FE-84
	Tracing system bitumen pipes in pump room and emergency sulphus pipes	16 794 C	THERMEX	CHA/SIE/FE-ES
	filting tracing system bitumen and emergency sulphur	13708€	Saint Nazeire Marine	
	connexion from thermex system to thermal oil system	2 468 €	Saim Nazairo Morine	
	old heating coils to remove on tritumen cargo pumps rooms	532.€	Saint Nazairo Marine	
	from cargo deck to lone and alt pump rooms, change steal pipes 3/4" to steel pipes 1" intel out tracing pipe	4 196 C	Saint Nazaira Marine	
95 000 €	Insulation of cargo lines, valves as per standards	quotation	Subcontrator	Comments
NAZAIRE OCT 05	Cargo pipes & valves insulation finalization	95 000 €	ARIS	
Section 10 to 10 t	PROV TOTAL	585 830 €		

	ANNEX 1					
	TRACING SYSTEM					
the tracing system designed pipes fitted as tracin	the tracing system designed by shipyard was based on wrong analys that the moltan sulpur is just circulating in cargo pipes. The very small pipes fitted with full steam tracing system.	he molten sul	pur is just ci	with full steam tracing syst	e very small	Annex
₽яуопсе ₹9/03	Foenforcement of heating systom after first প্রচর্তানতু ধিঃ: (২০৯৯/খণ্ড তা উপ্লয়ে কালছঃ)	1,803:14 E	THERMON	ethiogeat on Managura	TRA	mi
SY NAZAIRĖ 1875 10 25/26		1, 100:00 <u>e</u>	THERMON	412DB090F1 -N NOWABIRL	TRA	N
ST NAZARE 1808 to 2806	tépling system on sulgitur cango pumps filiais	10,794.00 €	HERNON	THERMON N° 1406308220	TRA	ပ
BAYONNE 19/03	Phimary heating on audur cargo (gnes.	\$ 007.989	SAREM	Sarem > 604628	TRA	4
BAYChaue 19703	Various valves to connect, primary thermas Cki on sulfur corgo pipes heating ซะเรีย 75 30 ร.	1,454,80 €	SPR:	SFR] N° F6884042	TRA	¢.
	Variuus valves to coanact in emergency primary thormal Ois on suffix congo pipes healing stolls.	1,020,00-6	SPEE	SPRI Nº FA606426	TRA	đ
ST NAZAIRE 1605 to 2606	paits for ckeck valves on main cergo pumpe dolivery. To maintain neni dif ष प्रथमकथा pump and mech seals	1,061.30 €	इक्ट _ा	SP83 N° F0806095	TRA	7
ST NAZAIRE 16/06 io 28/06	3 way valves to connect primary thermat Oil ca sulfur catgo lishes hading coils.	3,598,40 €	SP R	SPRI 8° F0606435	TRA	93
ST NAZAIRE 16/06 to 28/06	hight T' gaskes for tracing & chack valves	675,00 £	8P-R3	SPRI N° 60606219	ĪRA	ç
ST NAZAIRE 1806 to ZROS	night To gested for inspiring & check values	354.80 €	(SP4S)	SPRI N°F0808218	TRA	ö
ST HAZAIRE except for bitumers invo	tracing ayatem on euthir & Asphalt tines	112,693.00 €	XHMEHI	THERMEX Nº 18010 28160006	AST	
ST NAZAIRE excupt for bitumen line in CPR	tracing system on sulter & Asphalt Ines	21,742,85€	THERMEX	THERMEX Nº 18784 20060016	TRA	12
ST NAZAIRE except for bitumenting in CPR	দেৱনানু চystem on sulfur & Asphall lines	3,400,50 €	THERMEX	THERMID: Nº (8349) 20068909	TRA	ជំ
ST NAZARE except for bisemen line in CPR	tracing system on sultur & Asphen lines	10,400,00.€	THERMEX	THERMEX N° 180(8) 20569067	TRA	4
ST NAZARRE except for bitumen line in CPR	vacing system an ankur & Aspresi lines	33,507,00€	THERMEX	THERMEX IN 1800?	TRA	15
ST NAZARRE except for bitumen line in CPR	Therrex tracing system fitting based on 2 X 80 ML on deck & on 1 X 40 ML in Jump rooms as per Thermex	16,380.00 €	Sarri Nazsire Murine	N°06-5-1267	TRA	ä
ST NAZAIRE 1606 la 2806	Lilling device	4 (2.D) €	Saint Mazaine Marine	N966-1287	TRA	Ď
ST NAZARE except for bitumen line in CPR	Dismanting cutting of prevalue tracing	2,900.00 8	Saint Nazzire Marios	Nº46-6-126?	TRA	σñ
ST NAZAIRE 16/06 to 25:06	PTFE supply to insulate piece and support	1,050,00	Saint Nazzine Markne	%*Gà-4-1267	TRA	ត់
ST PLAZAIRE 16/06 to 26/06	Buikhead pelletration in FWO and AFT pureo room requel	810,00 €	Seiri Nazaire Wathe	8" (15.4; 126°)	TRA	ก็

5
ĭ
<u>.</u>
₹

572,534€

ZA/RIC except for bolumen line	Adjustment to serio pipes of THERMEX tracios	10,500,00 1	Spirit Variaine	N.98-4-1263	FRA.	e e
ZARE except for bilderen line	Adjustment to cargo pipes of THERMEX tracks			K-08-6-1267	TRA.	1 6
ST NAZAIRE except for bitumen line on CPR	Adjustrient to જ્યાપુર pipes of THERMEX ત્રવલગઢ	4,200.00 E		N°06-6-126?	TRA	á
ST NAZAJRE except for bituarien line in CPR	lscorsotric disawings	1,759.00 e	Saird Nazaire Marina	N°00-K-1267	TRA	Ġ
ST NAZAIRE except for biturner line in CPR	Overtime (to perform 12 D window)	2,925,00 €	Seint Nezsire Marina	N-95-6-3257	IRA	ō.
ST NAZAIRE 16/06 to 28/06	Various supply	7,862.00 €	Saint Mazaire Marine	N-86-4-1167	TRA	
ST MAZARE 1506 to 2886	Primary thermal oil on sulfor lines manitoring (PT 1000 serveurs)	1,712.00 €	Shiperec	X*2106369678	TRA.	27
	3 Way valves to consact emergency tracing to mein basing	2:342.00 €	SPK!	N° F0610175	TRA	28
	shuldown valve between primary and secondary kacing system	673,30 €	Spal	N° 50610367	TRA	29
	control of shuldown valve between primary and secondary tracing system	141.80 €	SPRI	N°F0610166	TRA	30
	fitting new HT 3 way valves on tracing system (including Shot Down)	5,100,00 €	Saint Nazako Marixe	hw N. 08 16 1808	TRA	3
	litting Shut Down valve	832.00 t	Sairt Negaire Madre	50 1509 to 1509	FRA	≌
	welding on pp room bulkead for tracing	€76.00€	Selni Nazaire Matine	inv 16° 98° 30° 1509	TRA	ម្ន
	Tracing system bilumen pipes in pump room and smergency subphur pipes	101,439.56 €	THERMON	N' 20080016	TRA	34
	Tracing system blumen pipes in pimp room and emergency suightur pipes	12,041.00€	THERNEX	N° 2008-601-5	TRA	35
	Tracing system bitumen pipes in pump room and emergenty subtrur pages	16,784,00 €	THERMEX	N° 20060835	TRA	36
	filting tracing system bitumen and emergency sulption	13,797.00 €	Saint Mazaire Marido	mr Nº 06 10 1509	īRA	31
	consexion from thermex system to freemel of system	2,700,00 €	Saint Nazzire Maxine	38.7 Nº 66 30 1509	TRA	ŭ
	oki heating coils to esmove on bilumeo cargo pumps toons	532.00 ¢	Sairt Nazaire Marine	187 Ne 10 1889	TRA	ä
	various spane for works, gaskers, fiorges, screw	3,920,00 €	Saird Nazairo Marine	inv Nº 06 10 1589	TRA	31
	New emergency pump	5,400:00 €	THERMEX OS	280640622788082)		43
SI NAZAIRE OCT 06	Cargo pipės & valvez insulation	46,526,00 €	ARIS	luv Nº 8121 t	TRA	45
ST NAZAIRE except for blumen line in CPR	Cargo pipes & visives insulations	51,930,6a £	ARIS	едкат	TRA	46
ST NAZAIRE except for bitumen line in CPR	Cargo ফ্রাহুল্ড ওঁ valves insulation	33,000,00 €	A PARS	60HZ6	TRA	47
ST NAZAIR® execpt for between lines in CCR	Cargo pipes & valves insulation	13,897.00 €	ARES	Inv No 62826	TRA	48

AUT CONDITIONS

					44,872 €	TOTAL AUT
33	AUT	60c Kr 06 10 1509)	Saimt Nazaire Masine	986.00 E	Cargo dip fray pargo pipes and valvas	
ä	AUT	inv Mr 96 20 4509	Ssint Nazake		pèpe to stop	
	AUT	NOT TO BE DONE	Saint Nazairo Marine	0.93	Boy Thrusiar safe access	
	AUT	DOME Free OC	Selet Maxeire Marine	88	Fwd watertight deors to be renewed	
	AUT	DONE Free DC	Seint Nurzire Marine	\$. 30 6	Landmarks on winch (60% SWL) & windless	SI HAZAIRE OUT OS
2	AUT	ETNA N°FC015982	ETNA	776.€	Bridge equipment posmréssionnéngtriafacts	ST NAZAIRE 2906
59	AUT	ETNA NºFC015º67	ETNA	1,589 €	Bridge equipment commissionning/defects	BAYONNE 19103
58	AUT	N°2006068671	Shipeies	2,056,50 €	ะกลู่กอคกักฏ and technical Re for BV and french Rug	ST NAZAIRE 1506 to 2806
57	AUT	N208686677	Shipelec	180.00€	visual & aാടിർ)ഭ remote alepho	ST NAZARE 1506 to 2806
56	AUT	N°7886060678	Shipelec	1,195,00 €	fraw relay panol for monote alarms	ST NAZARE 16/06 to 26/08
St.	Æ	N=2016060675	Shipelec	5,415,80€	shuldawa alarm on aliyo fara iBC oode	\$1 NAZAIRE 16/06 to 28/66
54	AUT	N°2006068670	Shipeiec	4,093 €	Upgrading of lighting of Pumproom bottom teval	ST NAZARE 16/06 to 25/06
53	AUT	N. SORKWERT, N.	Shipelec	4,523,40€	upgrading of Pump morn lighting/fon control (leval switch on/off)	57 NAZAIRE 16:06 16 29:06
(E)	AUT	N°2686660674	Shipelso	3,320,00 €	PC Cargo / PC ENGINE / Bridge connection	ST WAZAIRE 1605 to 28006
с т	AUT	X*2080806653	Shipeled	3 D07292'E1	gas dotection: remate suchble/visible alam on bidge & pumproam	ST NAZAIRE 1506 to 28/05
16	AUT	Nº06-4-1267	Sain) Nazaire Merine	560.00 E	Pws emergency ladder device	ST NAZAJRE 1600 to 28/06
16	AUT	Nº06-E-1267	Sant Nazaite Marino	2,150.50 €	Void Space supply of 4 vent beed filters to the fitted by ship's staff	ST NAZAIRE 16/96 to 28/06
36	AUT	Nº06-4-1267	Saint Mazaire Maribe	4,350,00 €	Cargo tank ventilotion shalf be ustrative (24h a day) at sext whatever condition: venthose by five most	st nazaire 1606 io 2806
	,	The state of the s	Sation of ted	nbay bumay or	ttems according to class, riag authority and vertifig requisitor or requirement	

CARGO PUMP SYSTEM

92	MU	\$10877	Par Sjertrum AS	2,550,00 €	Madianical asaks Utumen pung to soniew	- Anna Anna Anna Anna Anna Anna Anna Ann
10	#U4	JUNATA	Per Gjerdnim AS	9,550,00 G	Aƙaമ്പുഷമുട് seals sudur pump to reniew	
68	MUq	FAC 071723	និយាធ្លូវនៅពេក	₹,630.00 €	Mechnical books repair	
88	MUR	*(000)*	Busemens	13,317,16.6	Mecanical seas to reniew	
86	MUd	CHA-SIEFE-138-1 (abready paid on 109/02/2001)	Burgmano	18:216:00 6	Spare for mechanical series	
85	PUM	N. 2461	ರ್ಣಚಿತ್ರಗಳಿ	16,384,00 £	Salfur Cargo pump major teakage. Change of 4 mac. Seals.	ST NAZARE 1655 10 28/06 & BAYONNE 8/07
2 2	WÜA	Nº 16350	Burgmann	16,350,00 €	Sulfur Cargo pump major legitage. Change of 4 med. Seats.	37 NAZAIRE 1506 to 2506 & BAYCHNE 807
83	PUM	No 18930	Burghatte	21,594.00 €	Miscanical social parts	ST NAZAIRE 16/06 to 28/08 &
82	MUR	No. 42820	Burgmann	3,845,00 E	various spars parts after breakdowns	ST NAZARE 1600 to 2506 & BAYOWNE 807
8	MUR	N° 95285	មិបន្ទូលគូលរា	3,270.00 E	spars for meth skots repare	
80	WDd	N= 95934	Bugmans	18,972,00 €	Sulfur Carryo punnp major leekege mechanichul seats repare	ST NAZAIRE 16/06 IO 28/06 & BAYONNE BIOT
79	MUd	N° 92575	Burgmann	22,103,00 €	FWD Sulfur Cargo pump major leakage ! first disherging. Change of 4 mar. Seals.	ST NAZAIRE 16/05 to 28/05 & BAYONNE 8/07
78	MUS	Nº 93222	видохапп	3 87 050 T	SOB	ST MAZAIRE 16/06 to 28/08 & BAYONNE 8/97
77	PUM	N- 25%0	Bบะรูกาลกา	4,471,00 €	SOB	ST MAZARE 1606 to 2506 & BAYONNE 807
76	PUM	N° 92725	Burgenaan	1,056.95 €	30g	st nazare 1606 6 2806 a Bayonne B07
œ,	PUM	N-08-6-1267	Sair4 Nazaire Marine	9-00:08 6	Dismansling / Rofitling of 4 inlet steef expansion points	ST NAZAIRE 16406 to 28/06
16	PUM	Nº86-8-1267	Saint Nazairo Marine	5.473.00 G	Displacement Discharge valves of Cargo pumps	ST NAZAIRE 1600 to 28/06
6	Wind	N'06-6-1267	Saint Massire Marine	5,340.00 €	Stilly Asimo Asimo to peek to exist with sever	ST NAZAIRE 15/06 to 26/05
72	PUM	1097727	AGA	1,292,34.€	Hydraul Motor Parker for S. MAN Pump	88yarne 69/08
7	MUd	Nº 49859 CRA RM 131	Per Gjerdrum AS	5,885,00,€	hydrauli prop valve + SCB	Вауолев 09/06
70	PUM	Invoice (K) NF448892	Per Gjerdrum AS	2,100.00 €	2 sealing Oil pemp (following susphur leakage)	Delivery Sayonne 1907
63	MÜd	ENV N° 49986 CHA & 58	Per Gjerdrum AS	19.742.00 £	breakdown on alf sulphur pp change meck seals, spare parte, hot commissionning	bayonne la jorf 08/37/06 to 21/87/08
68	M≀⊓ď	laveice PG N°49866	Per Gjerdrum AS	740.00€	2 Inerriganethers	
67	PUM	hydixe PG N°48661 CHA RM SI/I	Per Gjerdhum AS	17.774.00 €	Caugo pump faiture.	Bayonsis 13/04 &14/04
66	PUM	CHA SIE FE 1971	Per Gjerdrum AS	4,439.00€	ocarmissionning during first call, parakineters utilicatement.	Bayonne 19703
	. Wrong s. Dueto	ck valves at delivery pumps) r, bitumen, emergency pump aling oil system.	ping (no che olten sulphu tant T' on se	gn og sargo pi em between n d and no cons	wrong commissionning of cargo pump mechanical seels, incorrect design og cargo piping (no check valves et delivery pumps). Wrong quality of sealing piping, Wrong (cheap) design of a commun seeling system between molten sulphur, bitumen, emergency pumps. Due to quality of sealing piping, Mrong kudanidining control design no constant speed and no constant T° on seeling oil system.	wrong commissionning o quality of sealing piping. W

																					AZAIRE OCT 05
boltom contros cargo piping modification for new bitumen cargo primps	suction and deliverypipes A valves modification for sulphur later & bilumen segregation	Filling of 2 Salesgency Billimen Puop	gasketts H T²	flanges for modification emergency piping	2 Bitumen Emengency Pumps	piping for new sensors	completion of connexions trials approbationss for tractife motors	parts for naw statisms and electric motors in place of hydraulic modes. Permanant problems with hydraulic control and speed on hydraulic motors	hitssy new cabbs, starters, for new electric motors, sensors	Bitumen cargo pumps Service On Board for commissioning	"RODIA" Dö ler Ikollen suphur cargo punsp first debv	piping and isolating valves on cargo pump hydraulic system	Austring of hydraulic lanes and new sealing lines as per PG and Bornemann request	Sealing Piping on Emergency butter purely as part PG/ Borrsomain recommendations (including air on tanks)	Sealing Piping on Silwisen pumps as per PGI Bornenasın reconsineadations (including air on tanks)	Seading Piping on sulfur pump ay per PG/ Bornemann recorrendations (including air ob lanks)	eixox union on mechanical yeals cargo riisin and emerijentsy pumps	Service and spare part \$1 Nazzere technical slop	4 et: molors 0.65kw for sealing pump & 1 fan cooling for PC Console	Electric rector 17 KW	Service on board and spair 2nd tech stop
6,00 €	7,322:00 (3,658.6	332.00	1,319 6	25,600,00 €	1, (40.00 g	Z,972,00 €	0.80	78,802.00 €	7,682.00 €	5,700 €	6,627.00 €	6,812.00	12,262:00 €	19,558,00 €	17,892.00	# 60 065	45,543.00 €	3,350.00 €	2,205,00 €	22,584.00 €
Saint Nazaire Marine	Seint Nazaira Manga	Saint triazairo Marine	37PE	SPRI	BLACKMER	Saint Nazzine Marine	SHIPELEC	SHIPELEC	SHIPELEC	Par Gjerdnam AS	RHODIA SILICONE	Saint Nazaire Marine	Saint Nazaire Morino	Saird Nazaire Marine	Saint Nazaire Marine	Sant Nezaire Marine	SPRI	Per Gjerdrum AS	Pe: Gjerdrum AS	Per Gjordnim AS	Per Gjerdrem AS
BACK COED	657 N° 06 16 1583	H+ N+ 06 14 E09	N° 269579	Nº F05101748	N° FA69009258 CHA/SIE/FE-98	6051 #1 90 aN Au	NY N° 2008 181 167	BKC7.UDE6 IN Nº 2066361150	BAA 2000 TO 1800	Jay Na 313491	30v No 90834813	EMS 1 BE 95 °N ARE	olifo No. (19. 10. 1885)	W N' 06 10 1509	104 M 06 10 1505	inv N° 76 10 1559	DAN SU EGY URM4	398206	X1690	\$0.5.50	50217
Mod	PUM	WDs	Mild	PUM	PUM	PUM	MUd	PUM	MUR	MUG	MOd	MPd	PUM	PUM.	Wind	MINA	MUd	PUM	PUM	PUM	MUS
4	37	9	115	174	113	9	=		109	10%	102	ដ	31	31	ಚ	31	101	100	97	98	95

					533,849 €	TOTAL PUM
4	PUM	Serem Nº 604028	SAREM	2,790.00 €	services and port for scaling piping after breakdown	
129	WUd	\$1770	ARIS	576.14 6	Sealing piping insulation	
128	PUM	CHYCHIL	406-21 6 Gonzales & fis CHA/OA-178	408.21 6	Sealing system	
4	PUM	Safety Nº 604028	SAREM	390.00 €	enginéts co lobard	
126	PCM	Sarem 3° 6043047	SARGM	4,830,00 €	soaling piping to change I renew efter breakthowns	
125	PUM	Nº FSK96419 / porški	SPRI	1,179,00 €	Bolt for theek valves	
120	MOd	Ipv Na 245 080 110	ENVC	5,450:00 E	Fitting of elec intuition on seasing pump / S MAN Pump (including bulkhead)	
31	PUM	385 N. 96 18 1263	Sairl Nazaire Manne	2,152.00 €	shipyard fogratic	
ä	PUM	50 N° 66 10 1509	Saint Nagairs Marine	1,118,00 €	Cargo purry screw bansport and packaging	
119	M.D.d.	CHA SIR FE 167	5,280 € BLOCKFLEX CHASIR FE 169	5,280 €	2' emergency flexible cango hose, surticer and delivery for emergency billines pumps	

	•														•	BAYoane Sept 06	ST NAZAIRE + Yearst to Bayonne	ST ALAZAIRE + Transit to Bayonne	ST NAZAIRE 16/06 to 26/06	ST NAZAJRE 1606 to 2806	8T NAZARE 16:05 to 28:06	ST NAZARE 16/06 to 28/06	RAYONNE 12/04	
Paint supply	Paint supply	Pasit supply	Paint supply	Fain sapply	Paint supply	Paint supply	Paint supply	Paint supply	Paint supply	Paint supply	Paku supply	Pains supply	Paint supply	Paint supply	Fixed gas detection repair	Claim 67 / Actuator for 3 W valve air coder ME	gear pamp for reduction good claim head office (4	SCANA SOB	Engine Pad Fas thange over (fail down)	engine toom fan cables and winng on statooerd side and port side	Port Alt Fan neisy and eir flow restrated by upper track	Engine Fas change over thing	Pawer Pack Failure	*XXXXXX
1,632.00 €	92€09€	3,224.00 €	1,014,40	505.60	*59,00	108.00	584 Sp 4	908.80	758.401	822.60	9,00,089,1	622,09	832.00	2,293.40 (4.774.9H B	1,122	3,287.78 €	9.134.41.6	4,793.00 €	¥, 186.00 €	12.00	1,980,00 €	425.20 €	
Hersey.	HEMPED.	TRANSE.	HEMPEL	HEWPET	HEMPEL	E HEMPEL	HEMPEL	HEMPEL	HEMPEL	HEMPEL	HEWPEL.	HEMPEL	HEMPEL	HEMPEL	Consilizan	PLEIGER	SCANA VOLDA VOJSIIKOSS	9,134,41 € SCANA VOLDA N°18081234	(ktab (supply	Shipelec	Sent Nazzire Marine	Saint Nazairo Marine		
NEWSET 4, 1855222	HEMPEL Nº 156059	HEMPEL N° 155253	36545EL N. 15265B	HEMPEL Nº 152539	HEMPEL N° 152657	MEMPEL Nº 1517777	HEMPEL N° 151842	HICKORD, N° 151862	HEMPEL N' 152295	HEMPEL N. 121858	HEMP#L N' 151892	HE4451 № 1248431	MEMPEC 10° 151989	HEMPEL N° 153464	CH*XXX-195	CHV8-9013	5/78(00) 58	N°18081234	ENAG N° 17966	N*780484406*2	Nº86-5-1367	N°08-4-1263	CHA/RM-45/ (
WAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	
153	152	151	150	149	148 bis	148	147	146	145	<u>.</u>	143	14.5	141	140	139	138	137	136	135	134	16	16	131	

Change scennalistion and pump room	crane failsce	cone tellos	Crane failure	Soller Graduing pump	Boiler sirculaling pump	ducting tydrolic piping	ਕਿਆਂ ਕੁਸ਼ੰ expenses + agency fees June dd	CLASS CONDITION	urgne failure estimation to dispact	ലര്വംളർന്നലൻ നേർ : פאלים מלימים מלימים אלים מלימים	cargo tanks verst pipes modifications	encidostions and new bypass emergency bensiler lines	Cardh fauil an main switch based		Auditie alamy CO2 SEXHORNS	Sarfy fauti on main switch board	Now "the JAPARET" (I mt only to protect the crains)	rmain engine daven sub oil gump oil pipe to enange	Extra Crew 2 dock boys in extra / 8 months	Paint supply	Pains sappès	Paint supply	Yaint supply	Pain supply
225.32	1,067.83	2,613.78	1,125.00 6	4,186,02 6	1,491,00	490.08 6	10,215.62	1,289.00	885.0ú é	2,068.00	3,180.00 €	5,740.00 €	3,334,00 ¢	•	2764.00 €	576.00 E	9,196.00 €	670.00 €	21,240,00 €	505,80 €	248.90 €	126.40 €	6 D41 30 €	158.00 €
225.32 F UNITOR	<u></u> इ	ACCACIA	Grues Laporte	COLFAX	COLFAX	DEKYSTSPOTT ER	Sea invest	87	885.00 é general diffusion 381/2006	ETNA	Sairi Nazare Marine	Spirit Nazgire Martne			SHIPELEC	SHIPPLEC	Sains Nozaire Marine	Saint Nozuine Marine		HEMPEL	HEMPEL	тэамэн	HEMPEL	HEMPEL
25CD26876	lov Nº 6072376	File duktios	Tav Nº FA1161	lwe N° 626015359	pp: Nº 67602168	Option if CHAISIEFS-72/1		Jan 14" 606,0064	368/2016	FC 016436	iny Nº 95 30 1509	fav 84,00 tu 500	BY N° 2006161368		69 110 E980T -N ANS	NV Nº 2008181306	Inv N° (8) t0 1509	1973 of 10 04 Aut		HEMPEL N. 152698	HEMPEL Nº 155264	HEMPEL N° 153465	HEMPEL Nº 153946	NEMPEL N° 155256
•••	VAR	VAR	VAR			VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	 ≱		VAR	VAR	VAR	VAR	VAR	VAR	VAR	YAR	VAR
184	183	180	179	177	176	175	174	173	171	168	31	31	:65		164	සි	냁	31		158	1577	156	155	154 154

AUT CONDITIONS
PUMPS
VARIOUS
INSULATION
TOTAL

166,750 € **1,499,058 €**

533,849 €

181,054 €

572,534 €

44,872 €

TRACING

		TOTAL INS						•	TOTAL VAR	ನೆಗಡೆ 19ಲೆ1 ತಿಡಿದ	Marseiles	Viane de Castelo	V)ลูกุด do Castelo	Ваустль	Bayonie	Baydenne	ваустве	Bayonne	Bayonne	
ENGAGED BY FSM FOR REPAIR			Iraang supply & distribution	tracing exculation	verd pipes molton sclipfor cargo lanks	thermal oil cargo tanks with volves boxes	themal oil tillumen primary	very bad quality of the protection of the piping insulation. MUST BE DONE	181,054 € INSULATION	High temperature thermal oil vakues	Claim Cerbes	CL 314 port wissass lignment	CL OIA donosard without synmeni	Cango reduces welding	Chiptery manifold	Display manifold	Chanwelk on esck piping	Catewalk on deck hydeolds piping	Anthor schackle break dawn	Cleating accomodation and pump room
		0 € 166,750.00 €				: "		e piping insula		2,403.00 ESPRI	2,634.00 €	30,500.00€	\$5,800,00 E	1,090,00	20.007	00.00B	1,480,50	1,289.00	3,10,00	259,02
		rts	SANB	ENVC	ENVC	ENVC	ewy.c	tion MUST B		espri	Siemans	Sud Mateurs	ENVC	1,090,00 ESAREM	700.00 ESAREM	660.00 & SAREM	1,460,00 C SAREM	1,260,00 #SAREM	310.00 € SAREM	259.00 F UNITOR
								EDONE	•	N= \$'0610250	COCIOCIDARSES	Involve to be received	011 8XB 042 9K NG	Succes Nº (640)?	Saren Nº 659046	Saren Nº 604016	Sareto SY 6(MB41	Sarem 74-609445	Sarem Nº 654828	2XCD26590
			ENS:	SNI	NS.	ĬN.S	NS.			VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	VAR	
			120	120	120	120	120			194	193		120	191	190	189	388	187	4	185
	والمناط	•																		



YARDIMCI GEMI INSA A.S. Aydintepe Mahallesi Tersaneler Caddesi 50 Sokak No.7 81700 Tuzla Istanbul Republic of Turkey,

Attn: Husseyin Yardimci

Marseille, 5 February 2009

Dear Sirs.

REF. FS CHARLOTTE EXHULL N°040 GUARANTEE UNDER ARTICLE IX

We hereby refer to:

- the acquisition contract dated 17 December 2003 (the "Acquisition Contract") entered into between FOUQUET SACOP SA as buyer (the "Buyer") and YARDIMCI GEMI INSA A.S. as builder (the "Builder") regarding the construction of one molten sulphur & asphalt tanker identified under Hull No 040 at the time of construction and presently known as FS CHARLOTTE;
- > Minutes of a meeting in Bayonne dated 6 June 2006 (a copy of which is attached);
- Our Guarantee survey report dated 11 & 12 June 2006 in Jorf Lasfar (a copy of which is attached hereto);
- > Our notice of defects dated 17 June 2006 (a copy of which is attached hereto);
- Our minutes of a meeting dated 19 June 2006 in Saint Nazaire (a copy of which is attached hereto);
- Our notice of defects dated 9 October 2006 (a copy of which is attached hereto);
- Our minutes of meeting dated 5 & 6 November 2006 (copy of which is attached hereto); and
- Our claims No 2 and No 14, re-issued on 5 September 2008, upon completion of corresponding repairs.

All corresponding claims have been addressed to your guarantee department in due time as per the Acquisition Contract.

As of the date hereof, we have not received any answer from you in respect of these claims, and your confirmation that they fall within the scope of the contractual guarantee.

112, bd des Dames 8,P. 24606 13567 Marseille Cedex 02

A breakdown of the costs of the repairs (with corresponding invoices) is attached in Appendix 1 hereto.

We now call upon you to confirm that you accept responsibility for the defects referenced herein and for the costs of all of the repairs in respect of such defects. Please confirm the same prior to close of business on 26 February 2009.

We should be grateful if you would also now send us payment in respect of these repairs, in the amount of EUR 1.499.058, corresponding to the actual costs borne by Fouquet Sacop for the repairs of the defective equipment on board FS CHARLOTTE. Please confirm that you will settle the same, also prior to close of business on 26 February 2009, and we shall be happy to provide you with bank details.

All of Buyers' legal rights and remedies arising under the Acquisition Contract or otherwise are hereby fully reserved.

Yours faithfully

Christiah Rouland

NORTON ROSE

27 February 2009

Private and Confidential

Mr. Husseyin Yardimci Yardimci Gemi Insa A.S. Aydintepe Mahallesi Tersaneler Caddesi 50 Sokak No.7 81700 Tuzla Istanbul

By e-mail and by courier

Your reference

Direct line

Norton Rose LLP 3 More London Riverside London SE1 2AQ

United Kingdom

DX 85 London

+44 (0)20 7444 2698

www.nortonrose.com

Tel +44 (0)20 7283 6000

Fax +44 (0)20 7283 6500

Our reference

DZPP/148/LN19892

Email

chris.hobbs@nortonrose.com

Dear Sirs

ST Charlotte - outstanding warranty claims under Acquisition Agreement dated 17 December 2003

We are London solicitors instructed to act on behalf of Fouquet Sacop S.A. in respect of their dealings with Yardimci Gemi Insa A.S., arising out of the Acquisition Contract dated 17 December 2003 for the purchase of the vessel, ST Charlotte (formerly the FS Charlotte). As you will be aware, further to your receipt of our client's letter dated 5 February 2009, there are various outstanding warranty claims in respect of the ST Charlotte which you have been requested to settle. You have been provided with full details and supporting documentation. We understand that you have failed to settle the same, notwithstanding your clear obligation to do so pursuant to Article IX of the Acquisition Contract. In fact, we understand that you have failed to respond to our client pursuant to their letter.

Our client should be grateful to receive your substantive response to their letter of 5 February, or, preferably, your settlement of sums due to them, as a matter of urgency. Kindly respond prior to 17:00 London time on Friday, 13 March 2009. If you are not prepared to consider our client's letter and settle its claim amicably, our client shall have little option but to commence formal arbitration proceedings against you pursuant to the terms of the Acquisition Contract.

We look forward to hearing from you.

Nortan Rose CVP

Yours faithfully

Norton Rose LLP

DRD-#5186931-v1

Norton Rose LLP is a limited liability partnership registered in England and Wales with number OC328697. It is regulated by the Solicitors Regulation Authority of England and Wales. A list of the members of Norton Rose LLP together with those non-members who are designated as partners and their professional qualifications is open to inspection at its registered office, 3 More London Riverside, London, SE1 2AQ. Any reference to a partner means a member of Norton Rose LLP or a consultant or employee of Norton Rose LLP or one of its affiliates with equivalent standing and qualifications.